

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐

2. NAME OF OPERATOR

Getty Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 730, Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: Unit letter <sup>E 1830</sup> ~~2~~-810' FNL & <sup>660</sup> 2080' FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

(other) Casing Connections

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Riser on 8 5/8" OD and 5 1/2" OD casing brought to surface.

Inspected by B. W. Weaver (NMOCC) on \_\_\_\_\_

Inspected by Mike Williams (NMOCC) on \_\_\_\_\_

Inspected by James Brasfield (USGS) on \_\_\_\_\_

Inspected by Bird Jones (USGS) on \_\_\_\_\_

RECEIVED

JUL 10 1979

O. C. C.  
ARTESIA, OFFICE

MAY 8 1979

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

D. R. Crockett

TITLE Area Supt.

DATE

MAY 8 1979

APPROVED BY

(Orig. Sgd.) JOE G. LARA

ACTING DISTRICT ENGINEER

TITLE

DATE

JUL 9 1979

CONDITIONS OF APPROVAL, IF ANY: