Form 9-331 Dec. 1973 N. M. O. C. COPT Form Approved. Budget Bureau No.					
Dec. 1973	UNITED STATES	••		Budget	Bureau No. 42-R1424
	DEPARTMENT OF THE INTER	RIOR	5. LEASE	NM - 23413	
gydwydy arlyw arder olliffilliae aid W. Ary Olein Ar va - 100	GEOLOGICAL SURVEY			N, ALLOTTEE O	
SUNDRY	NOTICES AND REPORTS	ON WELLS		REEMENT NAN	· · · · · · · · · · · · · · · · · · ·
(Do not use this fo	orm for proposals to drill or to deepen or n 9–331-C for such proposals.)			South Dee	
reservoir, Use rom	19–331-C to such proposals.)			R LEASE NAME	
1. oil well	gas (X) other		9. WELL NO	South Dee	p unit
2. NAME OF				20	<u> </u>
	o Production Company			R WILDCAT NAI	
3. ADDRESS (Drawer "A", Levelland,	TY		Empire - M	O TOW
4. LOCATION	4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17			-	e, option
below.)	1980' FNL and 2200' F	EL Sec. 12		12-18-28	
AT TOP PR	E: (Unit G SN뉳 NEԿ) OD. INTERVAL:		12. COUNTY Eddy	OR PARISH 1	3. STATE NM
AT TOTAL I	DEPTH:		14. API NO.		P 6 St
	PROPRIATE BOX TO INDICATE NA	ATURE OF NOTICE,			
REPORT, O	R OTHER DATA		15. ELEVATI 36	ons (show d 541:7 RDB	F, KDB, AND WD)
REQUEST FOR	·	NT REPORT OF:		# 17 A B	
TEST WATER S FRACTURE TRE		050	EIVET	6 4 3 4 A	
SHOOT OR ACI	DIZE 🗍	44 C D E	- 1 4 5 6		
REPAIR WELL PULL OR ALTE	LJ LJ R CASING D D	AUG 2		rt results of multi ge on Form 9–330	ple completion or zone
MULTIPLE COM	PLETE 🗍	AUG &	# 13/0		
CHANGE ZONES ABANDON*		0.1	s. c. 🤚	A & # 8	
	ıd <u>& set casing</u>		, OFFICE	8346	
17. DESCRIBE including es	PROPOSED OR COMPLETED OPER.	ATIONS (Clearly state sed work. If well is di	all pertinent rectionally dril	호텔스터 details, and gi led. give subsu	ve pertinent dates, rface locations and
measured a	nd true vertical depths for all marke	rs and zones pertinen	t to this work.)	*	
On 8-5-7	8 Sharp Drilling Co. (R	ig #37) spudde	d a 17½" ł	nole at 2:0	00 a.m. Drilled
to a ID o	of 390' and set 13 3/8 4	8# H-40 ST&C c	asing at 3	390' / Ce	ented with 200
down at 8	Thixset with additives 3:25 p.m. 8-5-78. Circu	and 400 Sacks (lated 50 sacks	MODE C	Toc.	TACL. Plug ted casing with
1500# for	30 minutes. Test OK.	Reduced hole	to $12\frac{1}{4}$ and	resumed?	drilling.
	30 minutes. Test OK.		//4	16.8 2 12.0	eie v
				Singlicht St	Micus Mari
			N. 3. 1	ESIA NEW ME	VIOOT.
			HKI		
Subsurface Safe	ty Valve: Manu, and Type			Set @	Ft.
18. I hereby cer	tify that the foregoing is true and cor				
SIGNED	ay W. Lox TITLE	Adm. Supv.	DATE	8-22-	78
	(This space	o for Federal or State office	ce use)		
APPROVED BY	Soe D. Lara TITL	CTING DISTRICT	ENGINEER.	AUG	2 3 1970
0+4 USG	S - Art 20-Partners		- 		VB SEIG
-1 - Div					
1 - Sus	•			rate a	
1 - RC	*See I	nstructions on Reverse SI	ide		