NO. OF COPICS RECEIVED	3			. •	Form C-103	
DISTRIBUTION			- 10 L P FROM 1980		Supersedes Old	
SANTA FE	7	NEW MEXICO OIL CONSE	RVATION COMMIS	SION	C-102 and C-103 Effective 1-1-65	
FILE	1/4-1.					
u.s.g.s.		JAN 2	5 1979	1 :	Sa. Indicate Type of L	.ease
LAND OFFICE			3 .0.0	7	State	Fco X
OPERATOR	7				5. State Oil & Gas Le	
	*************************************	U. 1	C. C. L. OFFICE			
	SUNDRY NOTIC	ES AND REPORTS ON V	VELLS		mmmm	mm
(DO NOT USE THIS FOR	AM FOR PROPOSALS TO	MILL OR TO DEEPEN OR PLUG BAN	CK TO A DIFFERENT RE	SERVOIR.		
1.					7. Unit Agreement Nar	r.c
OIL X GAS WELL	OTHER-					
2. Name of Operator		/ '			8. Farm or Lease Nam	e
Yates Pet	roleum Corp	oration √			Wright "JA"	
3. Address of Operator			*****		9. Well No.	
207 South 4th Street - Artesia, NM 88210					1 2	
4. Location of Well					10. Field and Pool, or	Wildcat
UNIT LETTER A 990 FEET FROM THE NORTH LINE AND 330 FEET FROM					Atoka Yeso	•
		· ·	_ CINE AND	FEET FROM	THITTIE	THITT
THE East	INE. SECTION 33	township18	S BANGE 2	26E NMPM.		
		, , , , , , , , , , , , , , , , , , , ,	E RANGE	<u> мири.</u>		
	(1111111)	15. Elevation (Show whether D	F, RT, GR, etc.)		12. County	77777
	<i>(1111111)</i>	3375'	GR		Eddy	
16.	Check Appropria	nte Box To Indicate Na	ture of Notice	Report or Oth	or Dota	7777777
	CE OF INTENTIO			SUBSEQUENT		
				SODSEQUENT	REPORT OF:	
PERFORM REMEDIAL WORK	1	PLUG AND ABANDON	REMEDIAL WORK		Atzenue	
TEMPORARILY ABANDON	j		COMMENCE DRILLING C		ALTERING CA	}===
PULL OR ALTER CASING	ĺ	() i	CASING TEST AND CEM	F=	PLUG AND AB	ANDORMENT [
	•		OTHER	A-1	,	
OTHER		·				
 Describe Proposed or Conwork) SEE RULE 1103. 	npleted Operations (C	learly state all pertinent detail	s, and give pertinent	dates, including e	estimated date of startin	g any proposed
s babburs	9-7/8" hol	e at 2:30 PM 12	_20 70			
				(20001)		_
		ints of 7" 20#				
3 central	.izers and 2	-cement baskets	. Cemented	as follo	ws: 250 sac	cks 50-
50 Poz 10	俳/sx Kolite	e, $1/4#/sx$ cello	flakes, 2%	CaCl. Ta	iled in $w/15$	50 sx
Class C 2% CaCl. PD 2:30 PM 12-30-78. Cement circulated 100 sacks to						
surface.		ours NU and test				
6½", dril						
$6\frac{1}{4}$ ", drilled plug and tested to 600#. OK. Resumed drilling. <u>TD 3105' - Ran a tapered string of production casing as follows: Ran 53</u>						
inints of	4½" 9 5# .	r-55 (2130') and	23 iointa	of Elm 14	H v ee /obel	
/mo+n1 21	. 4.2 σ.σπ ο	1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	23 JOINES	OL 32 14	H N-35 (9/5))
(IOCAL SI	.05) OI Cas	ing set at 3105	. Cemente	ed W/2/5 s	acks of Clas	SS C
cement.	Cement circ	ulated. PD 5:0	0 PM 1-16-7	79. WOC a	and tested to	1000#.
OK.					. •	
			•			
					•	
		₹'				
	-					
				•		
R I haralw contifu that the !-	Mormotles show the	ne and complete to the best of r				
X / moreby certify that the in	A STANDERSON ROOVE IS THE	t had complete to the best of i	пу Knowledge and be	Hef.		
(01/-1		•		•		
ICHED Areas	a Jonlin	TITLE Ge	ol. Secty		DATE 1-23-7	79

JAN 2 6 1979

CONDITIONS OF APPROVAL, IF ANY: