

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

RECEIVED

MAR 20 1979

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
Yates Petroleum Corporation

Address of Operator
207 South Fourth Street - Artesia, NM 88210

Location of Well
UNIT LETTER H 2310 FEET FROM THE North LINE AND 330 FEET FROM
THE East LINE, SECTION 33 TOWNSHIP 18S RANGE 26E NMPM.

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name
Wright "JA"

9. Well No.
1 3

10. Field and Pool, or Wildcat
Atoka Yeso

12. County
Eddy

15. Elevation (Show whether DF, RT, GR, etc.)
3364.8' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 9-7/8" hole at 12:30 PM 3-4-79.

TD 1131'. Ran 28 joints of 7" 20# J-55 (1131') of casing set at 1131'.
1-guide shoe at 1131'. Centralizer at 1090'. 2-centralizers and 2
baskets at 900' and 275'. Cemented w/250 sacks 50-50 Poz 2% gel, 3%
CaCl followed w/150 sacks Class "C" 2% CaCl. PD 4:15 PM 3-6-79. Cement
circulated 10 sacks to surface. WOC 18 hours. Nipped up and tested
to 1000#, OK. Reduced hole to 6-1/4". Drilled plug and tested to 600#,
OK. Resumed drilling.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine Ambrose TITLE Geological Secretary DATE 3-19-79

APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE MAR 21 1979

CONDITIONS OF APPROVAL, IF ANY: