M-G-F DRILLING Co., INC.

7TH FLOOR, VAUGHN BUILDING

MIDLAND, TEXAS 79701 915 - 684-7173

RECEIVED

MAY 23 1973

INCLINATION REPORT

D. C. C. ARTESIA, OFFICE

artesia 7. m. 88210 OPERATOR: Atlantic Richfield

LOCATION: Beauregard Unit No. 1 1980' FSL & 1980' FWL, Section 23. T-18-S, R-27-E, Eddy County, New

Mexico

Depth Feet	Inclination Degress	Depth Feet	Inclination Degrees	Depth Feet	Inclination Degrees
•					
405	1-1/4	5897	5	7533	2
1022	3/4	5939	4-3/4	7687	2-1/2
1500	1/2	5970	4-3/4	7802	2
2000	3/4	6031	5	7880	2
2500	3/4	6083	4-3/4	8058	2
3219	1/2	6146	4-1/2	8330	2
3716	1/2	6220	4	8576	2-1/2
4202	3/4	6313	4	8756	2-1/2
4605	1-1/2	6407	4	9122	2
4992	3-3/4	6499	3-3/4	9340	2-3/4
5060	4-1/4	6573	3-1/4	9477	1-3/4
5122	4-1/4	6625	3-1/4	9768	2
5185	4-3/4	6697	3	9972	2
5295	5	6746	2-1/2	10,270	1
5476	5	6808	3-1/4	10,270	T
5600	5-1/2	6880	2-1/4		
5654	5-1/4	6975	1-3/4		
5725	5-3/4	7057	2-1/2		
5786	5-3/4	7152	1-3/4		
5835	6	7275	2		
5866	5	7367	2-1/4		·

STATE OF TEXAS COUNTY OF MIDLAND

The undersigned state that he has knowledge of the facts and matter herein set forth and that the same are true and correct.

Norman VanLiew, Operations Manager

May

SUBSCRIBED AND SWORN TO BEFORE ME this the 11 day of

_____, 19₁₉₇₉

My Commission Expires:

July 31, 1980

Texas.

DISTRIBUTION /		RECEIVE	C-102 and C-103
ANTA FE /	N MEXICO OIL CONS	ERVATION COMMISSION	Effective 1-1-65
.s.g.s.		AUG 6 1979	5a. Indicate Type of Lease
AND OFFICE	•	4.55	State T Fee
PERATOR /	·	o. c. c.	5. State Oil & Gas Lease No.
		ARTESIA, OFFICE	B-3814
SUNDRY NO ONE THIS FORM FOR PROPOSALS USE "APPLICATION FOR	TICES AND REPORTS ON	ACE TO A DIFFFERENT BEFFERMALD	
OIL CAS WELL OT	HER-		7. Unit Agreement Name
Nume of Operator Yates Petroleum Corpo:	8. Farm or Lease Name Beauregard Com		
Address of Operator	taribanan arang dan kanan dan Taribanan dan kanan		9. Well No.
207 South 4th Street	- Artesia, NM 8	8210	1 1
Location of Well			10. Field and Pool, or Wildcat Uild .
UNIT LETTER K 1980	FEET FROM THE South	LINE AND FEE	T FROM I. Atoka Morrow Gas
THE West LINE, SECTION	•		NMPM.
	15. Elevation (Show whether is 3515 GR		12. County Eddy
Check Appro	priate Box To Indicate N	· •	or Other Data
ERFORM REMEDIAL WORK IMPORARILY ABANDON JILL OR ALTER CASING OTHER	PLUG AND ABANDON CHANGE PLANS	CASING TEST AND CEMENT JOB OTHER PERF & Tree	ALTERING CASING PLUG AND ASANDONMENT PAT Upper Zone X
TD 10287'; PBTD 10151 in packer at 9956'. and perforated 9691-9 perforations w/2000 g pulled packer at 9657	". WIH w/Wireling POH. WIH w/2-3/8" 8' w/14 .41" hole allons of acid and and RBP at 9742' ng, set packer at " choke at 900 MC	e and Standing Vatubing, RBP and s (2 spf). Set pd nitrogen. Los out of hole. RI 9656' Swabbed	well. Well cleaned up
JJJ4 10000 und opper	11022011 3032 30 1		•
		•	
			·
•		•	
		•	
i hereby certify that the information above i	is true and complete to the best of	f my knowledge and belief.	
10 Chritice To	Mhuson Hile G	eol. Secty	8-3-79
1.50 Ann	set St	IPERVISOR, DISTRICT II	AUG 7 1979
TOVED BY	TITLE		DATE
NDITIONS OF APPROVAL, IF ANY:	•		