

ower DD
tesia, NM 88210
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
2. NAME OF OPERATOR
Hondo Oil and Gas Company.
3. ADDRESS OF OPERATOR
P. O. Box 1710, Hobbs, N M 88241-1710
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1550' FNL & 660' FWL
AT TOP PROD. INTERVAL: As Above
AT TOTAL DEPTH: As Above
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

REQUEST FOR APPROVAL TO:

- | | |
|----------------------|--------------------------|
| TEST WATER SHUT-OFF | ☐ |
| FRACTURE TREAT | ☐ |
| SHOOT OR ACIDIZE | ☐ |
| REPAIR WELL | ☐ |
| PULL OR ALTER CASING | ☐ |
| MULTIPLE COMPLETE | ☐ |
| CHANGE ZONES | ☐ |
| ABANDON* | ☐ |
| (other) | ☐ |

SUBSEQUENT REPORT OF:

- | | | | | | | | |
|--|--|--|--|--|--|--|--|
| | | | | | | | |
|--|--|--|--|--|--|--|--|

☒ DST Upper & Lower Bone Springs

5. LEASE
LC-028772-b
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
RECEIVED
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal 10
9. WELL NO.
1
10. FIELD OR WILDCAT NAME
Undesignated
11. SEC., T., R., M.. OR BLK. AND SURVEY OR AREA
10-18S-28E
12. COUNTY OR PARISH
Eddy
13. STATE
NM
14. API NO.
30-015-23225
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3643.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- RU on 11/15/81, install BOP. RIH w/DP & circ & cond hole to 7836'. DST #4, Lower Bone Springs 6992-7055'. No test, unable to set pkr. DST #5, Lower Bone Springs 6992-7055', top pkr @ 6990', btm pkr @ 7056-, IHP 3371#, 15 min IFP 95.35#, FFP 669#, 52 mins ISIP 2619#, 36 mins 2nd flow, IFP 479#, FFP 954#, 23 mins FSIP 2581#, FHP 3331#, rec 2200 wtr, slight show gas. DST #6 Upper Bone Springs 4985-5140'. IHP 2477#, 20 mins IFP 46.7#, FFP 211#, 93 mins ISIP 1388#, 23 mins 2nd flow IFP 211#, FFP 211#, 37 mins 2nd SIP 1001#, 21 min 3rd flow IFP 900#, FFP 224#, 50 mins FSIP 1160#. FHP 2489#, rec 451' drlg mud, POH w/test tools. Bone Springs dry. Preparing to P&A on 11/21/81.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED James W. Schmidt TITLE Dist. Drlg. Supt. DATE 12/08/81

(This space for Federal or State office use)

PETER W CHESTER

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: 1981

U.S. GEOLOGICAL SURVEY
ROCKY MOUNTAIN, NEW MEXICO.

*See Instructions on Reverse Side