

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other Instructions on Reverse Side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028990

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CREEK

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

23;T18S;R30E

12. COUNTY OR PARISH 13. STATE
EDDY NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

ARROWHEAD OIL CORPORATION

3. ADDRESS OF OPERATOR

P.O. BOX 548, ARTESIA, NEW MEXICO 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface

250' FNL and 2350' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DE, RT, GR, etc.)
3492 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

16.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SPUD, CASING, & CEMENT

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded@ 6:00 P.M. on 9-16-81. Drilled 12 1/4" hole to 613', ran 610' of 8 5/8" 24# casing. Cemented w/375 sacks of class C 2% calcium chloride cement, circulated 70 sacks cement, plugged down @ 12:15 A.M. (9-17-81). WOC 18 hr. Pressure tested @ 1000 # for 30 minutes, it held okay.

TD @ 3550' on 9-27-81. Ran 3540' of 4 1/2" OD 10.5# casing. Cemented w/1000 sa of Halliburton light, salt mix 8#, gilsonite mix 5 #, floecle mix 1/2# and 600 sacks of class H, 5 # salt mix, CFR-2 mix-5/10 of 1 %, 10# of # 3 sand mix. Circulated 600 sacks. Plug down @ 1:00 A.M. on 9-28-81.

RECEIVED
OCT 5 1981

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

TITLE

Secretary

DATE

10-2-81

TITLE

DATE

*See Instructions on Reverse Side