TEST WATER SHUT-OFF

PULL OR ALTER CASING

(other) Spud & Surf.

MULTIPLE COMPLETE **CHANGE ZONES** ABANDON*

FRACTURE TREAT

SHOOT OR ACIDIZE REPAIR WELL

Form Approved.

Report results of multiple completion or zone change on Form 330.)

Budget Bureau No. 42-R1424

DEPARTM GE

DEPARTMENT OF THE INTERIOR	5. LEASE NM 13987
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Cobb-Federal
2. NAME OF OPERATOR	9. WELL NO. 2
Kenai Oil & Gas, Inc. 3. ADDRESS OF OPERATOR 79701	10. FIELD OR WILDCAT NAME
1001 Petroleum Bldg. Midland, Tx. 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22, T18S, R27E
below.) AT SURFACE: 2290' FNL & 330' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Eddy New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3468' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	

RECEIVED

- ARTESIA, OFFICE U.S. BEULUGIUAL SURVEY 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
 - Spudded 11" hole @ 7:45 pm 7-11-80 1.
 - Ran 11 jts 8 5/8", $20^{\#}$, ST&C casing and set at 465'. Cemented casing w/185 sax Class C + 2% CaCl₂. Plug down 3:00 pm 7-12-80, Circulated 25 sax to surface.

Subsurface Safety Valve: Manu. and Type	Set @	₋ Ft.
18. I hereby certify that the foregoing is true and correct		
SIGNED TILE Agent DAT	7-15-80	
(This space for Federal or State office use) ACTING DISTRICT EMONE CONDITIONS OF APPROVAL, IF ANY:	ER JUL 1 8 1980	