orm 9-331 N.M.O.C.D. COI	PY Form Approved. Budget Bureau No. 42-R1424 CISTAT
Dec. 1973 UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-070938 025604
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other 0.000 to 1000	Federal_BB 9. WELL NO.
2. NAME OF OPERATOR Amoco Production Company ~	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Box 68 Hobbs, NM 88240 STA OFFICE	Und. Scoggin Draw Morrow 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	
below) AT SURFACE: 890' FNL & 2245' FWL, Sec. 10 AT TOP PROD. INTERVAL: (Unit C, NE/4, NW/4) AT TOTAL DEPTH:	12. COUNTY OR PARISH 13. STATE Eddy NM
	14. API NO
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3510.2 GL
EQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
EST WATER SHUT OFF	
EPAIR WELL	(NOTE) Report results of multiple completion or zone change on Form 9–330.)
ULL OR ALTER CASING LI	change on Form 9–330.)
	/
HANGE ZUNES	n an an Anna an Anna an Anna an
	n an an Allen an All Allen an Allen an All Allen an Allen an All
BANDON* Fullewing other)	te all pertinent details, and give pertinent dates,
BANDON* E E. Lec.A, other)	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min.
 BANDON* Describe PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine On 7-9-80, Sharp Drilling Co. (Rig #63) spuce Drilled to a TD of 1003' and ran 48# H-40 13 Cemented with 1053 SX Dlass C cement with 23 7-13-80. Circulated 175 SX. WOC 22 hr. Test Test OK. Reduced hole to 12-1/4" and resume 	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling.
BANDON* Describe PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine On 7-9-80, Sharp Drilling Co. (Rig #63) spuce Drilled to a TD of 1003' and ran 48# H-40 13 Cemented with 1053 SX Diass C cement with 25 7-13-80. Circulated 175 SX. WOC 22 hr. Test Test OK. Reduced hole to 12-1/4" and resume O+4-USGS, A 1-Hou Subsurface Safety Valve: Manu. and Type	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling.
BANDON*	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling.
BANDON*	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling.
BANDON* Image: Figure 1 7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly static including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine 0n 7-9-80, Sharp Drilling Co. (Rig #63) spuce Drilled to a TD of 1003' and ran 48# H-40 13 Cemented with 1053 SX Class C cement with 23 7-13-80. Circulated 175 SX.WOC 22 hr. Test Test OK. Reduced hole to 12-1/4" and resume O+4-USGS, A 1-Hou I hereby certify that the foregoing is: true and correct GIGNED Bob Mark TITLE Admin. Analy	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling. 1-LBG 1-Arco St
BANDON* Image: Contract of the c	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling. 1-LBG 1-Arco St
measured and true vertical depths for all markers and zones pertine On 7-9-80, Sharp Drilling Co. (Rig #63) spuc Drilled to a TD of 1003' and ran 48# H-40 13 Cemented with 1053 SX C cement with 25 7-13-80. Circulated 175 SX.WOC 22 hr. Test Test OK. Reduced hole to 12-1/4" and resume 0+4-USGS, A 1-Hou Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED	directionally drilled, give subsurface locations and ent to this work.)* dded a 17-1/2" hole at 6:00 a.m. 3-3/8" casing set at 1003'. % CACL. Plugged down at 6:00 p.m. ted casing with 1000# for 30 min. ed drilling. 1-LBG 1-Arco St