

DISTRIBUTION		
SANTA FE	/	
FILE	/	✓
U.S.G.S.		
LAND OFFICE		
OPERATOR	/	

NEW MEXICO OIL CONSERVATION COMMISSION

Supersedes Old
C-102 and C-103
Effective 1-1-85

RECEIVED

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
E 1819	

SUNDRY NOTICES AND REPORTS ON WELLS AUG 18 1980

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		O. C. D. ARTESIA, OFFICE		7. Unit Agreement Name	
2. Name of Operator TENNECO OIL COMPANY ✓				8. Farm or Lease Name State JL-36	
3. Address of Operator 6800 Park Ten Blvd., San Antonio, Texas				9. Well No. 1	
4. Location of Well UNIT LETTER 0, 660 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 36 TOWNSHIP 18S RANGE 29E NMPM.				10. Field and Pool, or Wildcat Und. Turkey Track Atoka-Morrow	
15. Elevation (Show whether DF, RT, GR, etc.) 3435'				12. County Eddy	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded @ 6:00 P.M. 8/8/80.

Ran 7 jts of 13 3/8" 54.5# K55 8RSTC set @ 294.75'. Cemented w/315 sx class "C" + 2% CaCl₂. Cement didn't circulate during job - no cement back to surface. Y = 1.32 WT = 14.8 ppg. Cemented w/4 yards redi-mix. 13 3/8 x 20" Annulus stood full. Calculated top of cement ground level. Plug down @ 11:20 a.m. w/200 psi 8-9-80. WOC - 18 hrs. Tested casing w/1200 psi. O.K.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Mary Hall</u>	TITLE <u>Production Analyst</u>	DATE <u>8/13/80</u>
APPROVED BY <u>W. A. Gussitt</u>	TITLE <u>SUPERVISOR, DISTRICT II</u>	DATE <u>AUG 19 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		