. –		Jh
(June 1990) DEPARTMEN	T OF THE INTERIOR $N_{1}M_{2}$ DI	CONS. FORM APPROVED V-Dist. Englet Bureau No. 1004-0135 And 5 Avenuines: March 31, 1993 And 5 Avenuines: March 31, 1993
Do not use this form for proposals to dr	AND REPORTS ON WELLS Il or to deepen or reentry to a different reservo R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
I. Type of Well Oil Gas Well Other C. Name of Operator	Approved as to plugging of the well bore. Lightity under bond is retained while surface restoration is competed.	8. Well Name and No. Roche Federal #2 9. API Well No.
Mitchell Energy Company L.P. 3. Address and Telephone No. P.O. Box 4000, The Woodlands		30-015-23537 10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey D 1980 FSL and 1980' FEL of Se	scription)	N. Shugart, Bone Spring 11. County or Parish, State Eddy County, New Mexico
12 CHECK APPROPRIATE BOX	s) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTI	
Notice of Intent	Abandonment Recompletion	Change of Plans
	Plugging Back Casing Repair	Non-Routine Fracturing
Final Abandonment Notice	Altering Casing     Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vero		tarting any proposed work. If well is directionally drilled,
01-03-02 Cut 5-1/2" Csg. @ 4 01-03-02 Cut Csg. @ 3800', P 01-03-02 Spot 30 sx "C" cmt. 01-04-02 Spot 40 sx "C" cmt. 01-04-02 Spot 40 sx "C" cmt. 01-04-02 Spot 20 sx "C" cmt.	600', csg. not free. Spot 25 sx "C" OOH LD csg. inside csg. stub from 3860 to 3725 from 2195 to 2069'. from 705 to 579'.WOC & tag TOC @ 5 from 60' to surface.	', WOC & tag TOC @ 3705'.
01-09-02 Cut off wellhead. W	eid on dry noie marker.	RECEIVED OCD
14. I hereby certify that the foregoing is true and correct	Tide Agent	Date 01/07/02
(This space for Federal or State office use) Approved by (ORIG. SGD.) ALEXIS C. S Conditions of approval, if any:		
Accepted for record FEB 1 2002 only	"See Instruction on Reverse Side	United States any false, fictitious or fraudulent statement





KB: 3631.8' by CBL GL: 3617.3' EL: 14.5' API # 30-015-23537 LWZ # 636902-1

cmt w/ 780 sxs. No mud or cmt returns. WO cmt 5 hrs. Ran 1" pipe to 230' and pumped 50 sxs RFC. 1 hr ran 1", tagged at 169' broke circ and pumped 130 sxs.

DV tool @ 1702' 12/17/80. Circ'd 8 hrs. Cmt'd with 960 sxs 65/35 Poz and 200

cmt w/ 2700 sx. Full returns. Open DV tool and circ'd 155 sxs cmt to pit.

04/22/97 found csg leak 5250-5312'. Cmt'd with a total of 350 sxs cmt. DO but still had 35' per hour of fluid entry.

7708' - 7828' (142 holes), 2nd Bone Spring carbonate 2/9/91 acidized w/ 13,000 15% NEFE tagged w/ Iridium. Testing proved minimal carbonate prod, commingled with BS sand. 7865' (4 holes), sqz w/ 150 sx 02/05/91 pressure tested to 2000 psi 10 minutes

Perf'd 8275' -8346' (20 holes), 2nd Bone Spring sand 6/5/87 Acidized w/ 5,000 gals 7.5% HCL. Frac'd w/ 100,000 gals & 180,000# sd Final Report: 101 BOPD, 112 BWPD, Gas NA on pump.

Morrow tested 4.5 MMCFDG, 81 BCPD, 56.4 API, FTP 2072 psi

5-1/2", 17 ppf N-80 Butt 0'-1245', 17 ppf N-80 LT&C 1245'-10,152'

