

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

Alpine Petroleum Corp.

3. ADDRESS OF OPERATOR

Box 10507 Midland, TX 79702

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FNL & 660' FEL Sec. 24

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) various ☐

SUBSEQUENT REPORT OF:

☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐



OIL & GAS  
U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

5. LEASE

NM-12676

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Froehlich Federal

9. WELL NO.

10. FIELD OR WILDCAT NAME

Undesignated Wildcat Area

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 24, T-18S, R-21-E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
4073' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

5/30/81 Flow to pit. Swab, no recovery. SI for repairs

5/31/81 Flow & swab Release unit

6/01/81 Flow 6/02/81 SI for PBU 6/03/81 Open to pit

6/05/81 SI for PBU 6/06/81 Open to pit

6/07/81 Flow 100 mcf/d w/small stream water

6/08/81 SI 6/09/81 Open to pit. Light spray water w/acid odor

6/12/81 SI for PBU 6/17/81 Open to pit. Ran tbg to 4210' KB Reset tbg @ 4202' SI

6/23/81 Preparing to run 4 point test

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent DATE 6/23/81

APPROVED BY  
CONDITIONS OF

ACCEPTED FOR RECORD (This space for Federal or State office use)  
ROGER A. CHAPMAN

TITLE \_\_\_\_\_ DATE \_\_\_\_\_

APPROVAL, IF ANY:

JUN 29 1981

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side