BENNETT WIRE LINE SERVICE
Artesia, New Mexico 88210

SUBSURFACE PRESSURE MEASUREMENTS

COMPANY L. RAY DUNWOODY WELL NAME INNER NORTH #1
DATE OF TEST 7-18-81 TO 7-21-81 LOCATION PAGE 2 OF 2

CHART READINGS AND CALCULATIONS FOR BUILDUP OR DRAWDOWN TEST

DATE	HOUR	TIME	DEFLECTION in/inches	CALCULATED PRESSURE psig	CORRECTION P ± PC psig	CORRECTED PRESSURE psig	PRESSURE AT MID-POINT OF PERFORATIONS psig
7-19-81	15	0225		1,001	13.2		1,014
	20	0725		1,012	13.2		1,025
	25	1225		1,018	13.2		1,031
	30	1725		1,022	13.2		1,035
	35	2225		1,026	13.2		1,039
7-20-81	40	0325		1,030	13.2		1,043
	45	0825		1,034	13.2		1,047
	50	1325		1,038	13.2		1,051
	55	1825		1,040	13.2		1,053
	60	2325		1,042	13.2		1,055
7-21-81	65	0425		1,044	13.2		1,057
	69	0825		1,046	13.2		1,059