

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANTA FE               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATION              | 1 |

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501  
RECEIVED  
APR 08 1981  
O. C. D.  
ARTESIA OFFICE

Form C-103  
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSAL.)

|                                                                                                                                                 |                                                   |
|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>                                | 7. Unit Agreement Name                            |
| 2. Name of Operator<br>Yates Petroleum Corporation                                                                                              | 8. Farm or Lease Name<br>Young "PJ"               |
| 3. Address of Operator<br>207 South 4th St., Artesia, NM 88210                                                                                  | 9. Well No.<br>1                                  |
| 4. Location of Well<br>UNIT LETTER G 2310 FEET FROM THE North LINE AND 1650 FEET FROM<br>THE East LINE, SECTION 27 TOWNSHIP 18S RANGE 26E NMPM. | 10. Field and Pool, or Wildcat<br>Und. Atoka-Yeso |
| 11. Elevation (Show whether DF, RT, GR, etc.)<br>3330' GR                                                                                       | 12. County<br>Eddy                                |

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

|                                                |                                           |                                                                 |                                                             |
|------------------------------------------------|-------------------------------------------|-----------------------------------------------------------------|-------------------------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>                          | ALTERING CASING <input type="checkbox"/>                    |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>     | COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>     | PLUG AND ABANDONMENT <input type="checkbox"/>               |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>            | CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/> | OTHER <input checked="" type="checkbox"/> Production Casing |

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded a 9-1/2" hole at 11:05 AM 3-20-81.

TD 1120'- Ran 28 joints of 7" 20# ST&C K-55 casing set at 1120'. 1-regular pattern guide shoe at 1120'. Flapper insert float at 1080'. Cemented w/600 sacks 65-35 Poz, 4% Bentonite, 8# Kolite, 1/4# celloflakes & 3% CaCl. Tailed in w/150 sacks Class C 2% CaCl. PD 7:30 PM 3-22-81. Bumped plug to 500 psi, released pressure & float held okay. Cement circulated 10 sacks. WOC 18 hours.

TD 3100'- Ran 71 joints of 4-1/2" 9.5# J-55 casing set at 3093'. Diff-fill shoe at 3093'. Used 10 centralizers. Cemented w/350 sacks 50-50 Poz, .75% CF-2, .2% AF-HD & 2% KCL. PD 1:45 PM 4-1-81. Bumped plug to 1500 psi, released pressure & float held okay. Circulated 60 sacks to pit. Waiting on completion unit.

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

|                                 |                                    |                         |
|---------------------------------|------------------------------------|-------------------------|
| SIGNED <u>Arleta Goodwin</u>    | TITLE <u>Engineering Secretary</u> | DATE <u>4-8-81</u>      |
| APPROVED BY <u>M. Williams</u>  | TITLE <u>OIL AND GAS INSPECTOR</u> | DATE <u>APR 13 1981</u> |
| CONDITIONS OF APPROVAL, IF ANY: |                                    |                         |