

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR

Anadarko Production Company

3. ADDRESS OF OPERATOR

P. O. Box 67, Loco Hills, New Mexico 88255

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 2150' FNL & 840' FWL Sec. 8, T18S, R29E

AT TOP PROD. INTERVAL: Same Eddy County, New Mex.

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Spud, Drill T D, Set casing X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Moved in and rigged up rotary tools.
- Spudded 12 1/2" hole @ 8:30 PM 6-15-81. Drilled to 370'; did not lose circulation. Set 8-5/8" casing with casing shoe @ 363' KB & Halliburton cemented with 300 sx Class H w/2% CaCL. PD @ 9:30 AM 6-16-81; circulated 100 sx to pit. WOC 8 hours prior to nipping up Series 900 Double Ram Hydraulic Blowout Preventor. Pressure tested casing and BOP to 1000# psi.
- Began drilling shoe on 8-5/8" casing with 7-7/8" bit after 16 1/2 hours WOC. Drilled to 2775'; ran O. H. logs.
- Ran 5 1/2", 15.5# casing with casing shoe @ 2774' KB. Halliburton cemented with 400 sx Halliburton Lite w/8# Salt/sx & 1# Flocele/sx and tailed in with 250 sx Class H with 10# No. 3 Sand/sx, 5# Salt/sx & .5 of 1% CFR-2. PD @ 2:30 AM 6-23-81. Circulated 100 sx to pit.

Note: Will file appropriate forms upon completion of well.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Roger A. Chapman TITLE Area Supervisor DATE June 30, 1981

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD (This space for Federal or State office use)
ROGER A. CHAPMAN

JUL 2 1981

U.S. GEOLOGICAL SURVEY See Instructions on Reverse Side

5. LEASE

LC - 061702

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Ballard-Grayburg-San Andres Unit

8. FARM OR LEASE NAME

Tract No. 15

9. WELL NO.

7

10. FIELD OR WILDCAT NAME

Loco Hills-Queen-Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

8 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3535.7 G L

(NOTE: Report results of multiple completion or zone change on Form 9-331-C)

