

C/SF

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Drawer DD
Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
Forister & Sweatt ✓

3. ADDRESS OF OPERATOR
PO Box 161, Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2080 ENL 560 FEI ut H
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) casing & cement	<input type="checkbox"/>		<input type="checkbox"/>

5. LEASE
LC 062404

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
RECEIVED

7. UNIT AGREEMENT NAME
NOV 19 1982

8. FARM OR LEASE NAME
Hewitt *Fred* O.C.D.

9. WELL NO.
2 ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME
Loco Hills Q.GR.SA.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec 20 T18S R29E

12. COUNTY OR PARISH | 13. STATE
Eddy | New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3523 GR

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

NOV 17 1982

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- Spudded 11" hole 3:30 P.M. 10-30-82. Drilled 11" hole to 377'. Ran 9 jts 365' 28# K55 8 5/8" casing set at 377'. Cemented with 250 sacks Class C with 3% CalClor. Plug down 10:00 P.M. 10-30-82. Did not circulate - ready mixed to surface.
- Drilled 7 7/8" hole to T.D. 3100'. Ran 75 jts 3100.25' of 10.5# 4 1/2" casing set at 3100'. Cemented with 700 sacks Hal Lite with 12# salt 1/2# Flocele followed with 300 sacks Class C 50/50 Poz with 5# salt. Circulated 60 sacks to pit. Plug down 1:00 P.M. 11-5-82.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *David R. Glass* TITLE Partner DATE 11-16-82

APPROVED BY (ORIG. SGD.) DAVID R. GLASS DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD (This space for Federal or State office use)

NOV 18 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO *See Instructions on Reverse Side