

UNITED STATES MINERAL OIL CONS. COMMISSION
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, NM 88210

5. LEASE
LC-070003

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

APR 2 1982

8. FARM OR LEASE NAME
Mesquite 34 Federal

O. C. D.

9. WELL NO.
1

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME
Wildcat Miss

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 34, T-17S, R-31E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3767.2 GL

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR

Harvey E. Yates Company

3. ADDRESS OF OPERATOR

P. O. Box 1933, Roswell, New Mexico 88201

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FWL & 660' FSL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other) Spud & Surface csg & test

SUBSEQUENT REPORT OF:

RECEIVED
MAR 15 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/5/82 Spudded @ 7:30 a. m. 3/5/82. Depth 752'. Red Bed. Ran 18 jts 13 3/8" OD 48# H-40 Csg and set @ 752'. CMT w/300 sx Thich set plus 1/2# flocele, 10# Gilsonite & 2% CaCl/sx. Followed by 410 sx HLW plus 1/2# flocele, 5# Gilsonite & 2% CaCl/sx & 200 sxs Cl "C" w/2% CaCl. PD @ 1:45 a.m.

3/6/82 TOC 15' from Surface Topped out w/6 yds Redi Mix.

3/7/82 Cut off 13 3/8" csg. NU Csg head & BOP. After 18 hrs WOC tested BOP & Csg to 800 psi. - 30 min. OK.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Perk T. Linder

TITLE Engineer

DATE March 12, 1982

(This space for Federal or State office use)

APPROVED BY ROBERT A. CHAPMAN
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAR 19 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side