

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☐ well other ☒ **X-Water Injection**
2. NAME OF OPERATOR
Anadarko Production Company
3. ADDRESS OF OPERATOR
P. O. Drawer 130, Artesia, New Mexico 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FNL & 1600' FWL Sec.7, T18S, R29E
AT TOP PROD. INTERVAL: Same Eddy County, N. Mex.
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

X Spud; drill TD set & cement surface & production csg.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up rotary tools; spudded 12-1/4" hole with fresh water @ 8:00 AM 9-9-82; lost circulation @ 191'; dry-drilled to 358' KB.
2. Ran 8-5/8", 24#, K-55 casing with casing shoe @ 350' KB. Western Company cemented with 350 sx Class H w/27% CaCL. PD @ 4:45 PM 9-9-82; ready mix cement to surface.
Note: Danny Cortez with USGS witnessed cementing.
3. Installed Series 900 BOP and tested to 1000#. WOC total of 18 hours prior to drilling plug on 8-5/8" casing with 7-7/8" bit. Drilled to TD 2750' with brine water.
4. Ran 4 1/2", 10.5#, K-55 casing with casing shoe @ 2749' KB. Western Company cemented with 600 sx Pace Seller Lite w/8# Salt/sx & 1/4# Flocele/sx and tailed-in with 200 sx Class H w/5# Salt/sx, .3 of 17 TF4 & 10# No. 3 SF-4/sx. PD @ 6:30 AM 9-14-82; circ 100 sx to pit.

Note: Pete Hines with USGS witnessed cementing.

Will file appropriate forms upon completion of well.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *James E. Hines* TITLE Area Supervisor DATE September 16, 1982

ACCEPTED FOR RECORD _____ (This space for Federal or State office use)

APPROVED BY *D.H.G.* TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: OCT 4 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

5. LEASE

LC - 028772(a)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
**Ballard Grayburg
San Andres Unit**

RECEIVED

8. FARM OR LEASE NAME

Tract No. 1

9. WELL NO.

7

OCT 7 1982

10. FIELD OR WILDCAT NAME

**Loco Hills-Queen-
Grayburg-San Andres**

**O. C. D.
ARTESIA OFFICE**

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

7 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3620.4' GL

RECEIVED
OCT 17 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)