

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Artesia, NM 88214
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-01159	
2. NAME OF OPERATOR Southland Royalty Company ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 21 Desta Drive, Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1380' W 1980' FWL & 660' FSL, Sec. 4, T-18-S, R-30-E		8. FARM OR LEASE NAME Holly Federal #4	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3539.7' GR		10. FIELD AND POOL, OR WILDCAT Undesignated (Atoka)	
		11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 4, T-18-S, R-30-E	
		12. COUNTY OR PARISH Eddy	
		13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) Set 5 1/2" Production Csg. <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Drilled 7 7/8" hole to 11,675'. CCM to run csg. Ran 282 jts 5 1/2" 17# N-80 & S-95 LT&C and Buttress csg. Set @ 11,675'. Cmt w/600 sx Class "H" cmt 50-50 Poz mix and 600 sx Class "H" cmt. PD @ 10:35 AM 1-7-83. Set slips on csg. Remove BOP. Cut off csg. TOC @ 6745' by Temp. Survey. List of csg as follows:

Top	381	5 1/2" N-80 Buttress
	9465	5 1/2" N-80 LT&C
Bottom	1829	5 1/2" S-95 LT&C
Total	11,675	

RECEIVED
JAN 14 1983

OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

E. W. R. Glass
ACCEPTED FOR RECORD

TITLE District Operations Engineer

DATE 1-12-83

(This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY
CONDITIONS OF

JAN 14 1983

TITLE

DATE

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side