

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE*

(See other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0137
Expires August 31, 1985

WELL COMPLETION OR RECOMPLETION REPORT AND LOG *

1a. TYPE OF WELL: OIL WELL ☒ GAS WELL ☐ DRY ☐ Other ☐		1. LEASE DESIGNATION AND SERIAL NO. NM-01159	
b. TYPE OF COMPLETION: NEW WELL ☐ WORK OVER ☐ DEEP EN ☐ PLUG BACK ☐ DIFF. RENVR. ☐ Other <u>Reclass</u>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
2. NAME OF OPERATOR Southland Royalty Company		7. UNIT AGREEMENT NAME	
3. ADDRESS OF OPERATOR 21 Desta Drive, Midland, Texas 79705		8. FARM OR LEASE NAME Holly "4" Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements)* At surface 660' FSL & 1980' FWL, Sec. 4, T-18-S, R-30-E At top prod. interval reported below At total depth		9. WELL NO. 1	
14. PERMIT NO.		DATE ISSUED DEC -3 1986	
15. DATE SPUDDED 11-15-82		16. DATE T.D. REACHED 1-2-83	
17. DATE COMPL. (Ready to prod.) 11-20-86		18. ELEVATIONS (DF. RKB, RT, GR, ETC.)* 3589.7' GR	
19. ELEV. CASINGHEAD -		20. TOTAL DEPTH, MD & TVD 11,675'	
21. PLUG, BACK T.D., MD & TVD 10,890'		22. IF MULTIPLE COMPL., HOW MANY*	
23. INTERVALS DRILLED BY XX		24. PRODUCING INTERVAL(S), OF THIS COMPLETION—TOP, BOTTOM, NAME (MD AND TVD)* 10,485-10,627' Strawn	
25. WAS DIRECTIONAL SURVEY MADE Yes		26. TYPE ELECTRIC AND OTHER LOGS RUN Dual Laterolog, GR & RXO, CNL-FDC-GR-Caliper-BH Volume	
27. WAS WELL CORED Yes		28. CASING RECORD (Report all strings set in well)	
29. LINER RECORD		30. TUBING RECORD	
31. PERFORATION RECORD (Interval, size and number) 10,485-10,627'		32. ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.	
33. PRODUCTION		34. DISPOSITION OF GAS (Sold, used for fuel, vented, etc.) Sold	
35. LIST OF ATTACHMENTS C-103 & Plat		36. I hereby certify that the foregoing and attached information is complete and correct, as determined from all available records	

*(See Instructions and Spaces for Additional Data on Reverse Side)

