

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

NM OIL CON. COMMISSION

Drawer DD

Artesia, NM 88210

Form Approved.  
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill on or alter parts of land based on a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐

2. NAME OF OPERATOR  
Anadarko Production Company

3. ADDRESS OF OPERATOR  
P. O. Drawer 130, Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1709' FNL & 2234' FEL, 7-18S-29E  
AT TOP PROD. INTERVAL: Same Eddy Co., N.M.  
AT TOTAL DEPTH: Same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

SUBSEQUENT REPORT OF:

(other) Spud, Set surf csg, drill TD, set pdn csg. (Subsequent report) X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Rigged up rotary tools; spudded 12 1/2" hole with fresh water @ 5:30 PM 10-21-82; lost circulation @ 277'; dry drilled to 355'.
2. Ran 8-5/8", 24#, K-55 casing with casing shoe @ 351' KB; Western Company cemented with 350 sx Class H with 2% CaCL. PD @ 6:00 PM 10-22-82. Tagged cement @ 87'; ready-mixed to surface with 8 yards cement.
3. Installed Series 900 BOP and tested to 1000#. WOC total of 18 hours prior to drilling plug on 8-5/8" casing with 7-7/8" bit. Drilled to TD 2743' with brine water.
4. Ran 5 1/2", 15.5#, K-55 casing with casing shoe @ 2742' KB. Western Company cemented with 650 sx Pacesetter Lite w/5# Salt/sx & tailed in with 200 sx Class H w/.3 of 1% TF-4 & 10# No. 3 sand/sx. PD @ 1:45 AM 10-27-82; circulated 100 sx to pit.  
Note: Pete Hines with USGS witnessed cementing.  
Note: Will file appropriate forms upon completion of well.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Charles E. [Signature] TITLE Field Foreman DATE November 30, 1982

ACCEPTED FOR RECORD (space for Federal or State office use)

APPROVED BY (ORIG. SGD.) DAVID R. GLASS

CONDITIONS OF APPROVAL DEC 10 1982

MINERALS MANAGEMENT SERVICE  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side

5. LEASE  
LC 028772 D

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Ballard Grayburg San Andres Unit

8. FARM OR LEASE NAME  
Tract No. 3

9. WELL NO.

10. FIELD OR WILDCAT NAME  
Loco Hills-Queen-Grayburg-San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
ut. 9 7 - 18S - 29E

12. COUNTY OR PARISH  
Eddy

13. STATE  
New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3559.5' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)