		NM OIL CONS. C ISSIO	Form approved.	dist
Form 9-331 (May 1963) DEPAR	ITED STATES	Drawer Dit IN TA. LICATE		
	GEOLOGICAL SURVEY		LC-067132	
(Do not use this form for pro	DTICES AND REPORT	g ON WELLS ug back to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NA	ME
1.			7. UNIT AGREEMENT NAME	
OIL X GAS OTHER		r	1 10. (1999)	
2. NAME OF OPERATOR		MINTELSE	8. FARM OR LEASE NAME Denton Federal	
Ray Westall V		ROSVIELL, NEW MEXICO	9. WELL NO.	
	co Hills, New Mexico	88255	5	
4. LOCATION OF WELL (Report locatio See also space 17 below.) At surface	n clearly and in accordance with	any State requirem <b>RECEIVED</b>	10. FIELD AND WOOL, OR WILDCAT Junky Prach - Sh - 9 - 9 San Andres	
790 FNL & 990	FWL	DEC 171982	11. SEC., T., R., M., OB BLK. AND SURVEY OR AREA Sec. 27, T-18S, R-29E	
14. PERMIT NO.	15. ELEVATIONS (Show whether	er pF, hT, GR, etc.) O. C. D.	12. COUNTY OF PARISH 13. STATE	<u>-</u>
14, PERMII NO.	3463. GR	ARTESIA, OFFICE	Eddy N.M.	
16. Check		e Nature of Notice, Report, or (	and the second	
NOTICE OF IN			UENT REPORT OF:	
	[]		REPAIRING WELL	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING		
REPAIR WELL	CHANGE PLANS	(Other)		
(Other)		(NOTE : Report result: Completion or Recomp	of multiple completion on Well letion Report and Log form.)	
<b>1</b> 2-1-82	Gearbart perforate	ed 2874-84 ( 11 holes )		
<b>**</b> <sup>-</sup> 1 <sup>-</sup> 02	Gearmart periorate	2074 04 ( 11 hotes )		
		.5% NEFE Acid, 12 bbls. D#. Shut in at 150#. On		
		pulled one run, well s mall amount of oil.	tarted	
	Shut in pending ga	as hook-up.		
18. I hereby certify that the foregoin SIGNED Can e	ng is true and correct	Operator	DATE	
(This space for Federal Set	g_f_or_record			
	D.) DAVID R. GLASSE		DATE	
MINERALS MA Roswell	NAGEMENT SERVICE , NEW MEXICO *See Instruc	tions on Reverse Side		