

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR  
Yates Petroleum Corporation ✓

3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 660 FNL & 1980 FEL, Sec. 33-18S-30E  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐

5. LEASE

LC 028978-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME  
Benson Deep Unit

RECEIVED

8. FARM OR LEASE NAME  
Benson Deep Unit

JAN 05 1983

9. WELL NO.  
3

O. C. D.

10. FIELD OR WILDCAT NAME  
Wildcat Morrow

ARTESIA, OFFICE

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit B, Sec. 33-18S-30E

12. COUNTY OR PARISH  
Eddy

13. STATE  
NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3484.7' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 17-1/2" hole 2:00 PM 12-22-82. Ran 14 jts of 13-3/8" 48# ST&C J-55 casing set at 498'. 1-Texas Pattern notched guide shoe set 498'. Insert float set 459'. Cemented w/500 sacks Class "C" 2% CaCl<sub>2</sub>, 1/4#/sack flocele. Compressive strength of cement - 1050 psi in 12 hours. PD 7:00 AM 12-23-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 30 sacks. WOC. Drilled out 7:00 PM 12-23-82. WOC 12 hours. Cut off and welded on flow nipple. Reduced hole to 12-1/4". Drilled plug and resumed drilling.

RECEIVED  
DEC 29 1982

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED *David R. Glass*

Production Supervisor

DATE 12-28-82

Set @ \_\_\_\_\_ Ft.

ACCEPTED FOR RECORD

(ORIG. SGD.) DAVID R. GLASS

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL

JAN 04 1983

MINERALS MANAGEMENT SERVICE  
ROSWELL, NEW MEXICO

See Instructions on Reverse Side

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

