

c/s F

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660 FNL & 1980 FEL, Sec. 33-18S-30E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Production Casing, Perforate

5. LEASE

LC-028978-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Benson Deep Unit

8. FARM OR LEASE NAME

Benson Deep Unit

9. WELL NO. 3

O. C. D.

10. FIELD OR WILDCAT NAME

Wildcat Morrow

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit B, Sec. 33-T18S-R30E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3484.7' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 12055'. Ran 289 jts of 5-1/2" 20# & 17# N-80 ST&C casing as follows: 30 jts of 5-1/2" 20# N-80 ST&C, 235 jts of 5-1/2" 17# N-80 S&TC and 24 jts of 5-1/2" 20# N-80 ST&C (total 12079') casing set at 12055'. Super seal float shoe at 12055'. Super seal float collar at 12014'. Cemented w/500 sacks 50/50 Poz "H", .3% KCL, .4% CFR2 and .5% Halad-22. Compressive strength of cement - 850 psi in 12 hours. PD 6:30 AM 2-5-83. Bumped plug to 1500 psi, released pressure and float held okay. WOC 18 hours. WIH and perforated 11843-11853' w/40 .50" holes (4 SPF).

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct.

SIGNED: [Signature] TITLE: Production Supervisor DATE: 2-24-83

ACCEPTED FOR RECORD (This space for Federal or State office use)

(ORIG. SGD.) DAVID R. GLASS

APPROVED BY:
CONDITIONS OF APPROVAL, IF ANY:

DATE

MAR 04 1983

MINERALS MANAGEMENT SERVICE
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

