

April 17, 2001

New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division 811 South First Street Artesia, New Mexico 88210



Re: Fox #2 35-18S-26E API: 30-015-25071

Dear Sir:

I have enclosed your request of final items to be completed on the above referenced well. Hillside Oil & Gas, LLC has completed five of the six items for inspection. Item six was not checked, due to the fact we have left tank batteries out on the lease. We intend to put the Fox #1 as an injector. The property is located in section 35 T 18S R26E in Eddy County, New Mexico.

Sincerely

Jan South