

DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

## NOV 2 1985 SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. O.C.D. OIL WELL ARTESIAN WELL OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 36497	
2. NAME OF OPERATOR Dickson Petroleum, Inc. ✓ (Arlen Dickson, 915-686-9559)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR P.O. Box 50160, Midland, Texas 79710		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1724' FNL & 2279' FEL of Sec.13, T-18S, R-27E (Unit G) (SW/4NE/4)		8. FARM OR LEASE NAME Anadarko 13 Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3561' GR		10. FIELD AND POOL OR WILDCAT Artesia Oil Pool	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.13, T-18S, R-27E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1/8/85 Spotted 30 sx plug from 2050-2150'. 35 sx plug from 1275-1375'.  
95 sx plug from 290-450' with 4% CaCl Class "C".

Tagged at 390', 100 sx from 390' to 135'. Tagged plug at 135'.

9:00 A.M. January 8, 1985. Witnessed by Danny Cortez, BLM. Had verbal approval from Bob Pitsky.

1/25/85 Set 50' surface plug; installed dry hole marker.

2/14/85 Roland Construction Company filled in pits and cleaned location.

18. I hereby certify that the foregoing is true and correct

SIGNED Marlys ReynoldsTITLE ConsultantDATE 3/11/85

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE 11-21-85

\*See Instructions on Reverse Side