STATE OF NEW MEXICO	
ENERGY AND MINERALS DEPARTMENT DISTRIBUTION BANTA FE FILE ENERGY AND MINERALS DEPARTMENT OIL REQUSER VATTON DIVISION P. O. BOX 2018 SANTA FE FILE	Form C-103 Revised 19-1-78
ULG U J 1984 U.S.G.S. LAND OFFICE OPERATOR ARTESIA, OFFICE	Sa. Indicate Type of Lease State Fee X S. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS 100 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DECEDEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	7. Unit Agreement Name
1. OIL X GAS OTHER. 2. Name of Operator Yates Petroleum Corporation	8. Form or Lease Name Gates "AAC"
3. Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 2
4. Location of Well UNIT LETTER D 990 FEET FROM THE North Line and 990 FEET FROM	10. Field and Pool, or Wildcat Atoka San Andres
THEWest LINE, SECTION 22 TOWNSHIP 185 RANGE 26E NMPM.	
3348' GR	12. County Eddy
16. Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO: SUBSEQUENT	
PERFORM REMEDIAL WORE	ALTERING CASING

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1903.

Spudded 12-1/4" hole at 12:15 PM 11-19-84.

Ran 23 joints 8-5/8" 24# J-55 casing st 914'. 1-Texas Pattern notched guide shoe set 914'. Regular insert float set 872'. Cemented w/325 sacks Pacesetter Lite w/10#/sack Hi-seal, 1/4#/sack celloseal and 3% CaCl2. Followed with 150 sacks Class "C" w/2% CaCl2. Compressive strength of cement - 1250 psi in 12 hrs. PD 6:00 PM 12-1-84. Bumped plug to 1000 psi, released pressure and float held okay. Cement did not circulate. WOC 6 hrs. Ran Temperature Survey and found top of cement 310'. Ran 1". Tagged cement 310'. Spotted 50 sacks Class "C" 3% CaCl2. PD 1:45 PM 12-1-84. WOC 2 hrs. Tagged cement 119'. Spotted 75 sacks Class "C" 3% CaCl2. PD 4:30 PM 12-1-84. Circulated 10 sacks to pit. WOC. Drilled out 12:00 AM 12-2-84. WOC 18 hrs. Tested casing to 1000 psi for 30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

18. I hereby certify	that the information above is true and complet	e to the best of my knowledge and belief.	
inna	nto Dosdlitt	Production Supervisor	DATE 12-4-84
0	Original Signod By Lodie A. Clements Supervisor District II		DEC 07 1004
CONDITIONS OF A	PPROVAL, IF ANVI	717LE	DATE