Submit 3 Copies	State of New Mexico		Form C-103 45F+	
District Office	Ergy, Minerals and Natural Re	esources Department	Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088		Well API NO. 30 015 25928	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease	
<u>DISTRICT III</u> 1000 Rio Brazos Kd., Aziec, NM 87410			6. State Oil & Gas Lease No.	
SUNDRY NOT			NM 33437-A	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name	
1. Type of Well: OIL CAS WELL A WELL 2. Name of Operator	OTHER	RECEIVED	Roche Federal	
Enron Oil & Gas Company	y /		8. Well No.	
3. Address of Operator		JAN 25 '90	9. Pool name or Wildcat	
P. O. Box 2267, Midland	1, Texas 79702		Shugart Yates Seven Rivers	
	<u>0'</u> Feet From The <u>south</u>	O. C. D. ARTESHOOPERCE 660		
7		ARTESIDE and 000	Feet From The Cast Line	
Section /	Township 18S Ra	nge 31E	NMPM Eddy County	
	10. Elevation (Show whether	3640.9' GR		
	Appropriate Box to Indicate I		POT or Other Data	
NOTICE OF INT	ENTION TO:		SEQUENT REPORT OF:	
		REMEDIAL WORK		
		OTHER:		
 Describe Proposed or Completed Operative work) SEE RULE 1103. 	ions (Clearly state all pertinent details, an	d give pertinent dates, includ	ling estimated date of starting any proposed	
2025' to 207	5', sticking the drill	e 8-5/8" casing	Circ 102 sx to reserve pit. collapsed & parted from	
<u>10-20 ciriu 10-29-09</u> - I [,] W	ning on 8-5/8" casin	ig to 2073'. Pe Iring milling op	tire drill string intact. ices of the 8-5/8" casing erations inidcating the	
<u>10-30-89</u> ~ Prep to skid	drilling rig and dril	l new well.		
Roche Federal #3 was fl 2140' to 2154'. T-bing on December 8, 1989. T produce the Yates forma	owing oil from the Yat was run in the well t D 3235', PBTD 3235'. tion until it depletes	es formation at o a depth of 20 Detailed report <u>& then plug</u> an	intervals 2096' to 2102' and 09' and the well was completed attached. Plans are to d abandon this wellbore.	
I hereby certify that the information above a true	and complete to the best of my knowledge and i		nalyst	
TYPE OR PRINT NAME BELLY GI	ldon for Billy Helms		TELEPHONE NO. (915)686-371	
MIKE V	JAL SIGNED BY VILLIAMS A C		JAN 3 0 1990	
APPROVED BYSUPER	VISO9 2/STRICT 19 m	£	DATE	
CONDITIONS OF AFFROVAL, IF ANY:	Dereve Lev -		• .	

Oper: ENRON OIL & GAS COMPANY <u>8,575' Bone Spring</u> <u>EOG %: 42.857143 WI, 33.21428 NRI</u> AFE No. 0051190005 CPC: \$248,400, CWC: \$562,600 SC NO. N/A Product Call %: 42.857143

10-21-89 (5) PRESENT OPERATION: WOC

2482'; pmp #2 lnr & stroke 5-1/2 x 15; SPM 64; GPM 305; 1200#; MW 10; vis 29; pH 9.5; 5-1/2 hr RU Halib WL services; 2-1/4 hr TIH; 1 hr circ; 2-1/2 hr POOH, LD 8" DC; 4 hr RU csg crew, run 62 jts 8-5/8" J-55, K-55, total 2488'; set @ 2488'; 1 hr circ twice cap of csg; 1 hr cmt w/ B.J. Titan w/800 sx "C" lite w/10% salt & 1/4# celloflake, yield 1.86, 12.7 ppg; followed w/200 sx Cl "C" w/1/4# celloflake, yield 1.32, 14.8 ppg; did not bump plug circ 102 sx to reserve pit; Note: RD B.J. Titan, well started flowing cmt; wash up BOPE & close Hydril; press up to 200 psig w/rig pump; press incr to 300 psig; WOC 6-3/4 hrs; EDMC \$0; ETMC \$1,040; EDWC \$12,295; ETWC \$81,138

10-22-89 (6)

PRESENT OPERATION: Drilling

2800' (318'); 9-1/4 hr drlg; dolo; bit #3 7-7/8 HTC J44C H97HD; jets 12/12/12; in @ 2482' (318'); 9-1/4 hr drlg; 50,000#; RPM 40; pmp #2 lnr & stroke 5-1/2 x 15; SPM 66; GPM 326; 1400#; AV DP 196; DC 251; MW 8.8; vis 28; pH 11; 2 hr well closed in, ck press, 8:00 am 225#; 9 hr ND BOP, cut off.11-3/4".wellhead, weld on 8-5/8" x 11" 3000#, test head to 900 psi; 1/2 hr test blind rams & choke manifold to 2000 psi for 15 min-OK; 2-1/4 hr PU BHA, TIH; 1/2 hr test pipe rams w/2000#-OK; 1/2 hr drlg cmt, float collar, shoe; 9-1/4 hr drlg; EDMC \$240; ETMC \$1,280; EDWC \$6,629; ETWC \$87,767.

	<u>BHA</u>		
<u>Description</u>	<u>ID-IN</u>	<u>OD-IN</u>	<u>Length</u>
Bit		7-7/8	1.00′
3 pt BHR	2-1/4	7-13/16	6.48′
IB stab.	2-1/4	7-13/16	4.24′
Short DC	2-1/4	6-1/2	10.67′
IB	2-1/4	7-13/16	3.01′
1 DC	2-1/4	6-1/2	30.34′
IB	2-1/4	7-13/16	3.71′
28 DC	2-1/4	6-1/2	<u>811.14'</u>
TOTAL			870.59′

Oper: ENRON OIL & GAS COMPANY <u>8,575' Bone Spring</u> <u>EOG %: 42.857143 WI, 33.21428 NRI</u> AFE No. 0051190005 CPC: \$248,400, CWC: \$562,600 SC NO. N/A Product Call %: 42.857143

10-23-89 (7) PRESENT OPERATION: Working stuck pipe

3235' (435'); 11-1/2 hr drlg; anhy, dolo; 3/4° @ 2982'; bit #3 7-7/8 Hughes J44C H97HD; jets 12/12/12; in @ 2482' (753'); 20-3/4 hr; 40/50,000#; RPM 70; pmp #2 lnr & stroke 5-1/2 x 15; SPM 66; GPM 326; 1400#; AV DP 196; DC 251; MW 9.0; vis 28; pH 10.5; 5-1/2 hr drlg; 1/2 hr totco; 4-3/4 hr drlg; 2 hr trip to put 36 drill pipe rubbers on; 1-1/4 hr drlg; 4 hr made connection, had tight hole, worked to btm, pipe became completely stuck, pulled up to 170,000 total pull; 2 hr break out goose neck of kelly to run free point; 1/2 hr RU free point truck; 3-1/2 hr running free point; EDMC \$400; ETMC \$1,680; EDWC \$7,851; ETWC \$95,618.

10-24-89 (8)

(8) PRESENT OPERATION: Jarring on fish

3235' (0'); bit #3 7-7/8 Hughes J44C H97HO; jets 12/12/12; in @ 2482' (753'); 20-3/4 hr; pmp #2 lnr & stroke 5-1/2 x 15; MW 10.0; vis 29; pH 9.5; 5 hr work stuck pipe; worked pipe loose enough to pull 392' out of hole from 3235' to 2843'; work pipe pulling 100,000 over string weight of 110,000 pounds; 3-1/2 hr RU Kuykendall Electric WL Service; run free point; showed all drill pipe free; stuck at top of collars; POOH; TIH w/string shot; backed off leaving 1 jt of DP above collars @ 1954'; 1-1/2 hr TOOH; 4 hr caliper and PU fishing tools; PU 12 6-1/8" drill collars to fish with; GIH w/fishing tools & drill collars; gas cut oil and wtr kicking up thru fishing string; 1 hr PU kelly & circulate off gas using 10.0 ppg brine wtr; 1 hr strap in hole w/fishing tools:

Fishing tool Picture:

Length ft

3.23 screw-in sub 4-1/2 FH box x4-1/2 XH pin 6 OD x 2-1/4 ID 5.30 bumper sub 4-1/2 FH box x pin 6" OD x 2-1/4 ID 11.44 Houston Engin. jars 4-1/2 FH box x pin 5-3/4 OD x 2 ID 1.49 sub 4-1/2 XH box x 4-1/2 FH pin 6" OD x 2-1/4" ID 340.84 12 6-1/8 DC 4-1/2 XH box x pin 6-1/8" OD 2-7/16 ID 1.57 sub 4-1/2" FH box x 4-1/2 XH pin 6" OD x 2-1/4 ID 9.12 accelerator sub 4-1/2" FH box x pin 5-3/4" OD x 2" ID 1.82 sub 4-1/2 XH box x 4-1/2 FH pin 6" OD x 2-1/4 ID 374.81 TOTAL fishing tools

1/2 hr PU kelly & circ off gas using 10.0 ppg brine wtr; 1 hr fin strapping in hole; 1/2 hr screw into fish; 6 hr began jarring on fish; have moved fish 12' upward; bit was @ 2843'; now it is @ 2831'; EDMC \$0; ETMC \$1,680; EDWC \$4,417; ETWC \$100,035.

Oper: ENRON OIL & GAS COMPANY <u>8,575' Bone Spring</u> <u>EOG %: 42.857143 WI, 33.21428 NRI</u> AFE No. 0051190005 CPC: \$248,400, CWC: \$562,600 SC NO. N/A Product Call %: 42.857143

10-25-89 (9) PRESENT OPERATION: LD BHA

3235' (0'); bit #3 7-7/8 Hughes J44C H97HD; jets 12/12/12; in @ 2482' (753'); 20-3/4 hr; pmp #2 lnr & stroke 5-1/2 x 15; SPM 45; GPM 247; 600#; AV DP 145; DC 263; MW 10.0; vis 29; pH 10.5; 2 hr jar on fish; moved fish up hole another 2' to 2829'; had 5' of free rotation from 2829' down to 2834'; 1/2 hr RU to run free point at this depth; 1 hr attempt to rotate and drill out of the hole; tried this procedure with no results; 4-1/2 hr jar on fish; movement upward on fish from 2829' to 2739' (90'); 3/4 hr repair master chain in draw works; 9-1/4 hr work fish from 2739' to 1950' (789'); 3 hr TOH; LD 12 6-1/8" DC & fishing tools; 2 hr finish tripping out of hole w/original fish; LD BHA; all fish recovered intact; EDMC \$0; ETMC \$1,680; EDWC \$9,555; ETWC \$109,590

10-26-89 (10) PRESENT OPERATION: WO Mill

3235' (0'); MW 10; vis 29; 5-1/2 hr TIH w/7-7/8 swage; gas cut oil & wtr kicking up thru DC 4' to 12' high; 1/2 hr swaged from 2016' to 2026'; 1 hr swaging @ 2026;' w/no_success; 1-1/2 hr POOH; 1 hr TIH w/DC, bit & float; 5-1/2 hr inspect 28 DC in derrick, BHA, kelly, 12 DC (original fishing string) & 2 jts DP; 1 cracked pin & 1 cracked box included in original fish and 1 cracked box included in original fishing string; (NOTE: no problems with DC's in swage string); 3 hr TIH w/impression block to 2026'; take impression; 1-1/2 hr POOH; 4-1/2 hr WO mill; EDMC \$0; ETMC \$1,680; EDWC \$54,972, ETWC \$164,562

10-27-89 (11) PRESENT OPERATION: POH

3235' (0'); mill #1 pilot mill; pmp #2 lnr & stroke $5-1/2 \ge 15$; SPM 43; GPM 236; 250#; MW 9.3; vis 29; pH 10.5; 15 hr wait on mill; 2-1/2 hr PU pilot mill: 4-1/2" bull-nosed with 28" mandrel, then tapered to 7-7/8"; TIH to 2026'; 3/4 hr rig repair; 5-3/4 hr milled 2026' - 2035' (measured from btm of 7-7/8" cutting surface); mill rate incr'g from 1 to 2 ft/hr at end; 3000-4000# x 74-115 RPM; starting to POH; EDMC \$0; ETMC \$1,680; EDWC \$4,897; ETWC \$169,459.

Oper: ENRON OIL & GAS COMPANY <u>8,575' Bone Spring</u> <u>EOG %: 42.857143 WI, 33.21428 NRI</u> AFE No. 0051190005 CPC: \$248,400, CWC: \$562,600 SC NO. N/A Product Call %: 42.857143 mill #3

10-28-89 (12) PRESENT OPERATION: TIH w/mill #3

3235' (0'); mill #1 pilot mill; mill #2 7-7/8" tapered mill; mill #3 7-7/8" concave mill; pmp #2 lnr & stroke 5-1/2" x 15"; SPM 43; GPM 236; 250#; AV DP 107; DC 156; MW 9.2; vis 29; POH w/mill #1, move jars to 60'; TIH to <u>corrected</u> milling depth of 2045; milled from 2045'-2071' in 3-1/2 hr; PU 60' & lost 9' of hole to 2062'; worked 1 hr, no progress & high torque; POH w/mill #1; mill scarred full length plus 20' up first DC; move jars to 90' & TIH w/mill #2: 7-7/8" tapered; reamed 2036'-2066'/1 hr, then milled 2066'-2076'/5-1/2 hr with intermittent torque and spinning; POH w/mill #2; recovered 20" long strip of 8-5/8" csg tapering from 4" to 2-1/2", wedged in bottom of mill and wrapped around outside, mill was 3/4" out of gauge; TIH w/7-7/8" concave mil1; EDMC \$394; ETMC \$2,074; EDWC \$10,201; ETWC \$179,660.

10-29-89 (13)

PRESENT OPERATION: Milling on junk, milling depth 2073'

3235' (0'); mill #4 combination dress out pilot mill assembly; pmp #2 lnr & stroke 5-1/2" x 15"; SPM 43; GPM 236; 250#; AV DP 107; DC 156; MW 9.2; vis 29; 1 hr circ gas & oil after trip; 3-3/4 hr milling w/mill #3 (7-7/8" concave); 1-1/4 hr POH; 2 hr WO fishing tools; 1-1/4 hr PU 7" magnet w/mill tooth skirt & TIH; 1/2 hr magnet stopped at 2070'; 1-1/4 hr POH, LD magnet, rec 2 small pieces; 7-1/2 hr WO fishing tools; 1-1/2 hr PU mill #4 (mill #1 redressed) & TIH; 1 hr (time change) milling at 2069'; 4 hr milling 2070' to 2073'; EDMC \$551; ETMC \$2,625; EDWC \$9,659; ETWC \$189,319.

10-30-89 (14) PRESENT OPERATION: <u>Rig standby</u>

3235' (0'); MW 9.2; vis 29; pH 10.0; 2 hr TOH w/mill run #4 (combination dress out pilot mill assembly); recovered 4 small pieces of casing collar and two small pieces of casing that had jammed up inside bottom of mill; 3 hr LD fishing tools and WO orders; 19 hr cease fishing operations and place Cactus Rig No. 53 on standby @ 11:00 AM 10-29-89; well left in this condition: blind rams have been closed - well open through choke manifold to the reserve pit; EDMC \$0; ETMC \$2,625; EDWC \$9,566; ETWC \$198,885.