Submit 3 Copies to Appropriate En /, Minerals and District Office	ppropriate En /, Minerals and Natural Resources Department		
P.O. Box 1980, Hobbs, NM 88240 P.O.	1.0. D0x 2088		WELL API NO. 30-015-27394
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		5. Indicate Type of Lease	
		6. State Oil & Gas Lease No. 647	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name
1. Type of Well: OIL OIL OIL OIL OTHER WELL WELL OTHER 0003 2. Name of Operator 0003		Illinois Camp "17" State 8. Well No.	
Mewbourne Oil Company		11	
3. Address of Operator			9. Pool name or Wildcat
P. O. Box 5370 Hobbs, New Mexico 88241			IIllinois Camp Morrow, North Und.
Unit Letter : Feet From The West Line and Feet From The North Line			
Section 17 Township 18S Range 28E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3615' GR 3615' GR 3615' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING			
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed			
work) SEE RULE 1103.			
6-19-93: MIRU Peterson Drilling Company rig #3. Spudded 17 1/2" surface hole @ 8:30 PM 6-19-93.			
6-20-93: T. D. surface hole @ 385'. Ran 9 jts. of 13 3/8", 48#, J-55, new STC csg. and set @ 385' K. B. Halliburton cemented w/375 sks. of class "C" Lite containing 3% CaCl ₂ + 1/2#/sk. Flocele followed by 150 sks. of Class "C" Neet containing 3% CaCl ₂ . Plug down to 347' @ 7:40 AM 6-20-93. Curculated 73 sks. of cement to pit. Slurry volumes for lead slurry was 697 cu. ft. @ 12.8#/gal. and tail slurry was 202 cu/ ft. @ 14.8#/gal. Total slurry volume was 899 cu. ft. Compressive strength of tail slurry was 1350 psi in 12 hrs. @ 70° F. Estimated formation temp. was 69°F, est- imated slurry temp. was 78°F. WOC 14 hrs. NU BOP and pressure tested casing and stack to 600# for 30 min. each, all held 0. K.			
I hereby certify that the information above is true and complete to the best of my			
SKONATURE BUILT CENCE	m	P Drilling Sup	perintendent DATE July 7, 1993
TYPE OR PRINT NAME Bill Pierce			тецерноме но. 505 <u>393-5</u> 905
(This space for State Use) ORIGINAL SIGNED BY MIKE, WILLIAMS SUPERVISOR, DISTRICT		P	JUL 2 0 1993