

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries);				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TRUE VERT. DEPTH
San Andres Glorieta Yeso	1565	1842	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC... (continued from the front)	Seven Rivers	340'	
	3000	3098		Bowers	666'	
	3098	3424		Queen	855'	
				Casing	1329'	
				Grayburg	1330'	
				Premier Sand	1518'	
				San Andres	1565'	
				Alpha	1842	
				San Andres 'A'	2058'	
				San Andres 'B'	2136'	
				San Andres 'C'	2234'	
				San Andres 'D'	2296	
				Lower SA Porosity	2716	
				Glorieta	3000'	
				Yeso	3098'	
				B/Yeso Porosity	3424'	
				TD	3650'	

RECEIVED
2001 AUG 13 AM 8:49
BUREAU OF LAND MGMT
ROSWELL OFFICE