

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO
30-015-31620

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Ricks Exploration, Inc.

3. Address of Operator
210 Park Ave., Suite 3000, Oklahoma City, OK 73102

4. Well Location

Unit Letter D : 1980' feet from the North line and 660' feet from the West line

Section 1 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
GL: 3657' KB: 3675'

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☒

OTHER: Amended ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Well spud 5/22/01.

Drilled 17-1/2" hole to 398', set 13-3/8" 48# casing, cemented w/440 sx Class C. Drilled 12-1/4"

hole to 3099', set 8-5/8" 32# casing, cemented w/900 sx 50:50 POZ + 280 sx Class C. Drilled 7-7/8" hole to 9396', lost circulation. Set 8 cement plugs, total of 1360 sx with no success. Ran 7" casing & cemented w/300 sx. Cement top unknown.

Drilled out shoe w/full returns for 21 hrs. Continue to drill 6-1/8" hole to 10950'. Ran 4-1/2" P110 to TD. Cemented with a two stage, DV Tool @8394'. 1st stage 200 sx, open DV Tool, circulated 5 bbls of slurry to pit. 2nd stage, 400 sx, attempted to circulate cement to pit, however, outcome was only a trace of gray water to pit.

Well reached TD on 7/18/01.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lynne Suchy TITLE Drilling Asstnt DATE 10/01/01

Type or print name Lynne Suchy

Telephone No. 405/516-1100

(This space for State use)

ORIGINAL SIGNED BY TIM W. CUM
DISTRICT II SUPERVISOR

APPROVED BY [Signature] TITLE

DATE OCT 8 2001

Conditions of approval, if any: