

clsf  
Op

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.  
30-015-31719

5. Indicate Type of Lease  
State ☒ Fee ☐

7. Lease Name or Unit Agreement Name  
Yates As Fee Com

8. Well No  
#6

9. Pool Name or Wildcat  
Wildcat Chester

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL GAS  
WELL ☐ WELL ☒ OTHER

2. Name of Operator  
Yates Petroleum Corporation

3. Address of Operator  
105 South 4th., Artesia, NM 88210

4. Well Location  
Unit Letter K : 1550 Feet From The South Line and 1600 Feet From The West Line  
Section 25 Township 18S Range 25E NMPM Eddy COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER Intermediate Casing ☒

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Detailed Casing Report: Ran 27 joints 9-5/8" 36# 8R J-55 ST&C with special clearance couplings (1218.73') casing set at 1214" with Texas Pattern Guide shoe. Insert float set 1167.22'. Cemented with 200 sacks "H" with 10% A-10-B + 1/4# cellocel - 10# LCM - 1% CaCl2 (wt 14.6, yld 1.52) and 200 sacks BJ Lite with 1/4# cellocel - 5# LCM + 12% CaCl2 (yld 1.98, wt 14.8) Tailed with 200 sacks "C" + 2% CaCl2 (yld 1.34, wt 14.8). PD at 6:30 a.m. 5-30-01. Spotted 50 sacks Class c + 4% CaCl2. Stopped pumping at 1:00 p.m. 5-30-01. WOC 3 hours. Ran 1" tagged ceemnt at 567'. Spotted at 1:00 p.m. 5-30-01. WOC 3 Hours. Ran 1" tagged ceemnt at 567'. Spotted 50 sacks Class "C" with 4% CaCl2. Stopped pumping at 4:00 p.m. MST 5-30-01 WOB 2-1/2" hours. Ran 1". Tagged cement at 580'. Stopped 5 sacks Class "C" with 4% CaCl2. Stopped pumping. Spotted 260 Sacks. "C" - 1% CaCl2. Drilled out at 3: a.m. 6-0-01. Reduced hole to 8 #/4" and resumed drilling. Nofified Phil Hawkins at OCD in Artesia of cemented temperature survey. Reduced hole size to 7-7/8".

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Operations Technician DATE 11/8/01

TYPE OR PRINT NAME Erma Y. Gutierrez TELEPHONE NO 505-748-1471

APPROVED BY [Signature] TITLE DISTRICT II SUPERVISOR DATE NOV 16 2001

CONDITIONS OF APPROVAL, IF ANY: