

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

RECEIVED
JUL 1 1949

Oil Cons. Comm.

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	<input checked="" type="checkbox"/>
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	<input checked="" type="checkbox"/>	REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL			

June, 29, 1949

Artesia, N. M.

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

R. W. Fair

Santa Fe

Well No. 1

in the

Company or Operator

Lease

22-24-NW

of Sec. 22

T. 19S

R. 26E

N. M. P. M.,

Wildcat

Field,

Eddy

County.

The dates of this work were as follows: May, 17 through May, 23, 1949

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____ 19____
and approval of the proposed plan ~~was~~ (was not) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

On May, 17, 1949 at total depth of 1798' an attempt was made to acidize porous oil stained zones, showing only rainbow, 1550' to 1558' and 1614' to 1637'. Formation packer was run on 3" tubing and set at 1504' water used on top of packer, 1000 gal. acid was used, job was failure account packer failed to hold. On May, 18 another attempt was made to acidize with 1000 gal. pressure was applied to 8" casing and at 600# cement broke down around casing shoe, acid job was a failure. On May, 19, the 8" casing was re-cemented with 45 sacks cement using Halliburton equipment. On May, 23, 1949 plug was drilled and water shut-off was found to be complete.

Witnessed by Harold Kersey

Kersey & Co.

Owner

Name

Company

Title

Subscribed and sworn before me this _____

day of May 19 49

Notary Public

I hereby swear or affirm that the information given above is true and correct.

Name

L. M. Arnold

Position

Sup't.

Representing

R. W. Fair

Company or Operator

My commission expires

Address 711 Dallas Ave. Artesia, N.M.

Remarks:

Name

ARTESIA REPRESENTATIVE

Title