

# OIL CONSERVATION COMMISSION

207 CARPER BUILDING

ARTESIA, NEW MEXICO

July 27, 1960

J. S. Ward & Son, Inc.  
101 S. Fourth St.  
Artesia, New Mexico

Dear Sir:

I am writing in regards to two wells on which you are wanting to cancel bonds.

1. Chambers & Kennedy, Delhi St. #1, Unit N, Sec. 35-17-28E, Eddy County, N.M. On a recent inspection of this location, we found no location on marker. It should read: SE $\frac{1}{4}$  SW $\frac{1}{4}$  Sec. 35-17-28. The pits, cellar and rat hole are not filled.
2. N. R. Williamson, Phillips St. #1, Unit N, Sec. 12-19E-27E, Eddy County, N.M. - This well was inspected June 24, 1960. We found dead men loops not cut and the location not cleaned.

Very truly yours,

M. L. Armstrong  
Supervisor, District No. 2

MLA/hb

cc: Oil Conservation Commission  
Santa Fe, New Mexico