

NEW MEXICO OIL CONSERVATION COMMISSION

DRAWER DD

ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Jones & Hails</u>		Lease <u>Featherstone St</u>		Well # <u>1</u>	
Location of Well	Unit <u>NW 3E</u>	Section <u>32</u>	Township <u>19</u>	Range <u>27</u>	County <u>Eddy</u>
Drilling Contractor	Type of Equipment				

APPROVED CASING PROGRAM

Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement

Casing Data:

Surface _____ joints of _____ inch _____ # Grade _____
(Approved) (Rejected) _____

Inspected by _____ date _____

Cementing Program

Size of hole _____ Size of Casing _____ Sacks cement required _____

Type of Shoe used _____ Float collar used _____ Btm 3 jts welded _____

TD of hole 560 Set 3 1/4 Feet of 7 Inch _____ # Grade _____

New-used csg. @ _____ with _____ sacks neat cement around shoe

+ _____ sax _____ additives _____

Plug down @ _____ (AM) (PM) Date _____

Cement circulated _____ No. of Sacks _____

Cemented by _____ Witnessed by _____

Temp. Survey ran @ _____ (AM) (PM) Date _____ top cement @ _____

Casing test @ _____ (AM) (PM) Date _____

Method Used _____ Witnessed by _____

Checked for shut off @ _____ (AM) (PM) Date _____

Method used _____ Witnessed by _____

Remarks: Kermit Hoover Plugging Contractor

453' 5 1/2 pipe in hole none pulled, had cement plug from TD to 440' when inspector arrived, water from 440' to 370'. Bridged off at 370' with dirt & rock, ran 11 1/2 sacks cement on top of bridge @ from 370' to 260 feet.

R. L. Stumbo
July 17, 1961