

Stephens & Johnson Operating Co.
East Millman Pool Unit No. 6-5
Eddy County, New Mexico

4-16-2002

Well Data

Surface Casing: 8 5/8", set @ 270' w/50 sx cmt
Production Casing: 4 1/2", 9.5 lb/ft, set @ 2235'
w/160 sx cmt. TOC @ 1535'

Perforations: Queen 1740-1744'
1770-1776'
1939-1945'

Grayburg 2106-2112'
2150-2156'

CIBP: Set at 1595'. Production casing is filled
with corrosion inhibited fluid.



Casing Integrity Test Procedure

04-04-2002

Pressured casing to 580 psig. In 30 minutes
pressure had dropped to 570 psig. (Copy of
pressure chart attached.) Capped well for TA
status.