

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company John A. Yates		Address 323 Garper Bldg., Artesia, N. Mex.			
Lease Caroline	Well No. 5	Unit Letter D	Section 28	Township 19 S.	Range 28 E.
Date Work Performed 3-10-62	Pool East Millman Seven Riv.		County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain): **Perforating and fracturing.**
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated 4 1/2" casing from 1126 to 1130 with 3 shots per foot. Acidized with 15000 gallons of acid. Fractured with 500 barrels lease oil and 50000# sand. After recovering load oil and acid water, well pumped 25 barrels oil and 10 barrels water in 24 hours.

RECEIVED

APR 9 1962

D. C. D.
ARTESIA, OFFICE

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P BTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by *M. L. Armstrong*
Title **OIL AND GAS INSPECTOR**

Name *Mela Gunder*
Position **Bookkeeper**

Date **APR 9 1962**

Company **John A. Yates.**