

August 9, 1962

John A. Yates
323 Carper Bldg.
Artesia, New Mexico

Re: Caroline #7, Unit #1
Sec. 28 19S-28E
Sddy County, New Mexico

Dear Sir:

Before we can sign the plugging release on the above described well it will be necessary that you fill the pits and remove the tie downs.

Oil Conservation Commission

Very truly yours,

REL/jw

Howard E. Lebley
Oil & Gas Inspector

1947

1947
1948
1949

1947
1948
1949

1947

1947
1948
1949

1947

1947

1947

1947
1948

1947