



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lesse No. MM 0932

Unit RECEIVED

MAR 9 1961

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		
	Plugging	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 16, 1959

Anderson
Well No. 1 is located 1980 ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and 660 ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec. 31
SW/4 NW/4 Section 31 19S 28E 10PM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcat Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Mudded hole from 1050' back to 950'. Set 10 sack cement plug - mudded back to top of 7" casing at 240'. Set bridge and 10 sack cement plug and mudded back to surface and set marker in cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Schuster & Schuster

Address Box 305

Artesia, New Mexico

By Harold Kusey

Title Agent

