

## FIELD TRIP REPORT

Name RAY SMITHDate 3-1-94 Miles 113 District     Time of Departure 7 ATime of Return 4 P Car No. 07

In the space below indicate the purpose of the trip and the duties performed, listing wells or leases visited and any action taken.

5-19-25 Irate for Nicholas #1. To witness P.H. operations on the above well. RTH w/ plug & perforations.

M-36-19-28 Billy R. Wilson Plot A-1. Drive to location to check plugging operation. Pull out of hole w/ prod equipment.

MileageUIC     RFA     Other 113Per DiemUIC     RFA     Other     HoursUIC     RFA     Other 8

## TYPE INSPECTION PERFORMED

## INSPECTION CLASSIFICATION

## NATURE OF SPECIFIC WELL OR FACILITY INSPECTED

H - Housekeeping  
P - Plugging  
C - Plugging Cleanup  
T - Well Test  
R - Repair/Workover  
F - Waterflow  
M - Mishap or Spill  
W - Water Contamination  
O - Other

U - Underground Injection Control - Any inspection of or related to injection project, facility, or well or resulting from injection into any well. (SWD, Indry injection and production wells, water flows or pressure tests, surface injection equipment, plugging, etc.)  
R - Inspections relating to Reclamation Fund Activity  
O - Other - Inspections not related to injection or The Reclamation Fund

D - Drilling  
P - Production  
I - Injection  
C - Combined prod. inj. operations  
S - SWD  
U - Underground Storage  
G - General Operation  
F - Facility or location