	PIES RECEIVED	5.									
NUMBER OF CO							VATION PORTS D			FORM C-103 (Rev 3-55)	
PRORATION O	GAS	3	(Submit to	o approp	oriate Dist	rict Office	as per Cur	nmission R			
Name of Con	ipany Jol	m A. Yat			Add	ress 323 Ca	rper Bl	dg. A	artesia Tesia	., N.;Mex.	
Lease	lizabeth	Dundes	Well	1 No.	Unit Lett		Township	198	Range		
Date Work P 9-18-61	erformed	Pool	Undesig		1		County	ddy		478	
7 20 04			THIS IS A F			ck appropri					
Beginn	Beginning Drilling Operations Casing				d Cement	lob	X Other (Explain): Perforating and				
🔲 Pluggir	Plugging F			emedial Work of materials used, and results ob			fracturing.				
Witnessed by	Witnessed by Position						Company				
· · · · ·		FIL	L IN BELOW		REMEDIAL		EPORTS OF	NLY			
DF Elev.	F Elev. T D		PBTD				Producing Interval		Cor	Completion Date	
Tubing Diam	Tubing Diameter Tubir		bing Depth		Oil S	Oil String Diameter		Oil String D		)epth	
Perforated In	terval(s)	······							<del></del>		
Open Hole Interval						Producing Formation(s)					
	·····			RESUL	TS OF WO	RKOVER			·		
Test	Date of Test		Oil Production BPD		Production CFPD		Production BPD	GOR Cubic feet/Bbl		Gas Well Potential MCFPD	
Before Workover											
After Workover								 			
		ERVATION CO	OMMISSION				fy that the in my knowled,		iven above	e is true and complete	
Approved by	Approved by M. + (in the						Name Mala Cardan				
Title	VIL AND GAS	INSPECTOR	F		Pos	ition	okkeep				
Date	<u>G</u>	T <sup>2</sup> 1961			Cor	npany	hn A. Y				