

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company John A. Yates				Address 323 Carper Bldg, Artesia, N. M.			
Lease Elizabeth Dundas		Well No. 2	Unit Letter N	Section 7	Township 19S	Range 29E	
Date Work Performed 2/9/62		Pool E. Millman Green Sh. Undesignated			County Eddy		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
☐ Plugging
 ☐ Remedial Work
 Perforating and fracturing

Detailed account of work done, nature and quantity of materials used, and results obtained.

Perforated 4½" casing from 2101 to 2096, and from 2087 to 2080 feet with 12 shots per foot
Fractured with 714 Bbls. lease oil and 58000 # sand, running 500 gallons acid ahead of fracturing.
After recovering load oil, test showed well pumping 20 Bbls. oil and 100 Bbls. water

RECEIVED

APR 17 1962

O. C. C.
ARTESIA, OFFICE

Witnessed by	Position	Company
--------------	----------	---------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>M. L. Armstrong</i>		Name <i>John A. Yates</i>	
Title OIL AND GAS INSPECTOR		Position Bookkeeper	
Date APR 17 1962		Company John A. Yates	