- Draver 13. CC. Arts	Clise , C
Tresia, 11 882	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
JUN 01 100 AARTMENT OF THE INTERIOR	LC-058709 (b)
O. C. D. GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
STEND OFFICE AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331–C for such proposals.)	8. FARM OF LEASE NAME
1. oil gas well 🖾 well other	9. WELL NO.
2. NAME OF OPERATOR	14
GRSJ PETROLEUM	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Shugart (Y.SR,Q,G.)
P.O. BOX 6, LOCO HILLS, NEW MEXICO 88255 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below)	
AT SURFACE: 1980' From N line & 660' From W li	192. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Eddy New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE.	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	3741' $A$
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE	
	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING [_]	change on Form 9-330.)
ABANDON*	
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and
This well was shut in when purchased.	
Pulled rods and pump and found rods parted.	
Repaired pump, replaced 1 rod and reran pump an	d rods.
Flushed well with 60 barrels fresh water and st	arted pumping.
This well is making approximately 3 barrel per	day.

----

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
<b>18.</b> I hereby certify that the foregoing is true and correct SIGNED And Star TITLE <sup>CO-Owner</sup> DATE	5/23/84
ACCEPTED FOR RECTOR Date for Federal or State office use)	Ε
alstad, NEW MEXICO	