	UNTED STATES TO THE INTERICAL OF LAND MANAGEMENT	cr.11	
(Do not use this form for prop Use "APPLIC	TICES AND REPORTS Of the design of the desig	· · · · ·	6. IF INDIAN, ALLOTTEE OR TEIBE NAME
OIL GAS OTHER			7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR William A	Edward R. Hudson.	MAY 18 '89	8. FARM OR LEASE NAME Shugart "R"
3. ADDRESS OF OPERATOR		O, C. D .	9. WELL NO.
P.O. Box 9. Maljamar, New Mexico 882764 CONFICE 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT
1980' from north and 660' from east lines of Sec. 15-185-31E			Shugart Queen - G-G-11. SBC., T., E., M., OR BLE. AND SURVEY OR AREA
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	Sec. 15-18S-31E 12. COUNTY OR PARISH 13. STATE
16. Charl. A		(N) (N)	Eddy N.M.
Check Appropriate Box To Indicate Nature of Notice, Report, or C NOTICE OF INTENTION TO: 8UBBBOUT			Uther Data UENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
REPAIR WELL	ABANDON* CHANGE PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT*
(Other)		(Note: Report results	s of multiple completion on Weli eletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) •			
On April 25, 1989, 3262', spotted cemmud to 2050', spot salt gel mud to 80 a cement retainer surface through period on top of cement retainer water, placed 60' marker with well of June 2, 1989 Valley Electric water aroung the well wi	O, the location was as notified to remoill be re-seeded be ready for final i	bridge plug in 3212', loaded ho 50' to 1950', lo /2" casing w/4 st 850', circulat (Used 200 sks.) to 700', filled ace, installed 4 cleaned of all we two power poletween June and S	le with salt gel aded hole with hots at 890', set ed cement to the , spotted cement hole with fresh "x 8' dry hole debris. Central es. The area
SIGNED Service -	fluere TITLE Pr	od. Supt.	DATE 5/3/89
APPROVED BY CONDITIONS OF APPROVAL, IF	NY: TITLECHIEF, A	MINERAL RESOURCES	DATE 5 15 89
Approved as to pullify an in the Liebility under trend its returned un surface restoration is completed,	*See Instructions of	on Reverse Side	Part ID-2 5-26-89 Pr A