

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office LC
Lease No. 029393B
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

2-15, 1949

Well No. 1B is located 1980 ft. from N line and 1920 ft. from W line of sec. 17
SE 1/4 11 11 (Twp.) 18 S (Range) 31 E (Meridian)
North Shugart (Field) Edy (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

filled w/ mud and set 15 sack plug on bottom of 7" knocked 7" off at 1800 feet and set 10 sack plug at top of 7" stub. mud to bottom of 8 5/8" at 715' down set 10 sack plug in bottom of 8 5/8" then mudded to top and set 4" marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Edy

Address _____

By W D Ballien
Title (owner)

