	(.13)			
Form 9-331 Dec. 1973 UNITED STATES Artesia, NM 88210 5.	Form Approved. Budget Bureau No. 42-R1424			
UNITED STATES Artesia, M. 5.	i. LEASE			
DEPARTMENT OF THE INTERIOR	NM-10193			
GEOLOGICAL SURVEY 6.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
(Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME RECEIVED 3. FARM OR LEASE NAME			
	East Shugart Unit			
	P. WELL NO. FEB 0 9 1983			
2. NAME OF OPERATOR ARCO Oil and Gas Compary	28			
Division of Atlantic Richfield Company V 10.	D. FIELD OR WILDCAT NAME O. C. D.			
	Shugart Yates & A +BPE614, OFFICE			
P. O. Box 1710, Hobbs, New Mexico 88240 11.	I. SEC., T., R., M., OR BLK. AND SURVEY OR			
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA			
	34–18S–31E 2. COUNTY OR PARISH 13. STATE			
AT TOD DOOD INTERVAL	Eddy New Mexico			
	4. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				
REPORT, OR OTHER DATA 15.	5. ELEVATIONS (SHOW DF, KDB, AND WD)			
3	3616' CTF			
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF	(NOTE: Report results of multiple completion or zone change on Form 9–330.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RU, install BOP, POH w/compl assy. Ran bit & csg scraper to 2585'. Tagged fill @ 2647'. Set cmt retr @ 2514'. Cmt squeezed OH 2591-2647' w/retr @ 2514'. Cmt sqzd OH 2591-2647' w/250 sx Cl C cmt cont'g 2% CaCl2. Spotted 25' cmt on top of retr. Tagged TOC w/wireline @ 2489'. Ran CBL 2489' to surf. TOC behind 7" csg @ approx 1840'. Perf'd 7" csg @ 930' w/4 shots. Circ hole w/gel 10# brine, Set cmt retr @ 806'. Circ cmt between 7" x 8-5/8" annulus w/150 sx Cl C cmt. Circ 30 sx to pit. Dumped 75 sx on top of retr. Set 10' cmt @ surf. Cut off well head below GL, installed regulation dry hole marker, cleaned & levelled location. P&A eff 4/17/82. Final Report.



Subsurface Safety Valve: Manu. and Type				<u>11 8. C. Set @</u>	Ft.
18. I hereby certify that the foregoing is true and correct			KUGAY, L, KLW A LACO		
SIGNED Dory Dechnick	ITLE Dist.	Drlg.	Supt, DATE	4/26/82	-
(Orig. Sgd.) PETER W. CHESTER	space for Federal				
FEB 8 1983				Post 7	D-7 82
JAMES A. GILLHAM DISTRICT SUPERVISOR	See Instructions o	n Reverse S	Side	r	4 m