

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

NMOT 01-177451a

C/SF

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other WIW

2. Name of Operator
DEVON ENERGY CORPORATION (NEVADA)

3. Address and Telephone No.
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611

4. Location of Well (Footage Sec., T., R., M., or Survey Description)
990' FNL & 2310' FWL Sec. C-35-18S-31E

5. Lease Designation and Serial No.
NM10190

6. If Indian, Allottee or Tribe Name
N/A

7. If Unit or CA, Agreement Designation
14-08-001-11572

8. Well Name and No.
East Shugart Unit #6

9. API Well No.
30-015-05696

10. Field and Pool, or Exploratory Area
Shugart (Y-SR-Q-G)

11. County or Parish, State
Eddy, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input checked="" type="checkbox"/> Other <u>Integrity Test</u>
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran mechanical integrity test 11-14-94. RU pump truck and load csg w/water. Pressure tested csg to 510 psi for 30 mins. OK. Chart attached. Witnessed by J. D. Whitlock (BLM).

APR 20 1995

We currently have a line drive waterflood pattern in operation on the west side of the unit. It is anticipated that 18 months will be required to evaluate the performance of the pilot. At that time, the well will either be returned to active injection status or P&A'd. We request TA approval until that time.

TA APPROVED FOR 12 MONTH PERIOD
ENDING 4/17/96

14. I hereby certify that the foregoing is true and correct

Signed Candace R. Graham Title CANDACE R. GRAHAM
ENGINEERING TECH.

Date 4/13/95

(This space for Federal or State office use)

(ORIG. SGD.) **JOE G. LARA**

Title Petroleum Engineer

Date 4/17/95

Approved by
Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

