


APPROVED



RONNIE E. SHOOK
ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office Las Cruces

Lease No. 069041

Unit A

Copy to 57

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 3, 1964

Carper Federal "A"
Well No. #1 is located 660 ft. from (N) line and 990 ft. from (E) line of sec. 4
NE/4 NE/4 Sec. 4 18S 31E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Shugart Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging, cementing points, and all other important proposed work)

On February 23, 1964, this well was plugged and abandoned as follows:

Loaded hole with water. Placed 40 sacks of cement from 3600' to 3300'. Placed 10 sack plug at surface with 4" marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John D. Sanford

Address 302 Carper Building

Artesia, New Mexico

By Ralph L. Gray

Title Consulting Engineer.

