

APPROVED
SEP 19 1961
A. J. SHUPIN
ACTING DISTRICT ENGINEER

C. G. G. H.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**

Lease No. **304-00007-1-B**

Unit _____

SEP 21 1961

**D. C. C.
ARTESIA OFFICE**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 10, 1961

Donnelly-Pan American
Well No. 1 is located 2310 ft. from [N] line and 2510 ft. from [E] line of sec. 5
3X **SW**

SW NE/4 Sec. 5 T19S 31E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Undesignated Eddy New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3667 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On July 7, 1961 we recovered all of the 782' - 8 5/8" OD 3/4" S.N. Casing which had been run and mudded in the hole. Cement plugs were placed as follows:
35 sx - Approx. 100' at 800' - 900'
35 sx - Approx. 100' at 2100' - 2200'
35 sx - Approx. 100' at 2600' - 2700'
Marker has not been set as it will be in way in skidding substructure back while moving rig from present sight. Location not yet cleaned nor pits filled. These requirements will be reported when done.

RECEIVED

JUL 11 1961

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Donnelly Drilling Co., Inc.**

Address **P. O. Box 433**
Artesia, New Mexico

By *[Signature]*
Title **Operator**