

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Los Cruces

Lease No. 029353

Unit **RECEIVED**

SEP 22 1947

SUNDRY NOTICES AND REPORTS ON WELLS **U. S. G.**
ARTESIAL OFFICE

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT & Plugging <input checked="" type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 13, 1947

Well No. 2 is located 2310 ft. from N line and 330 ft. from E line of sec. 24

N. 24 of 24 19S 71E N.M.P.M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Lusk New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3547 ft.


DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Mixed Mud and set Cement Plug with 30 Sacks Cement from 2650' to 2500'.

Set another Cement plug at 2100' - Used 10 Sacks Cement. Set Cement

Plug at 850'. Used 15 Sacks Cement.



TD 2876-PB 2650

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Plains Production Company

Address 1110 Tower Petroleum Building,

Dallas 1, Texas.

By [Signature]

Title Agent